
Table of Contents

Information Resources

Subject	Page
Information Resources	4
Service Information Bulletins	4
Service Actions and Recalls	5
Service Action	5
Recalls	6
Repair Instructions	7
Vehicle Technical Diagnosis (FTD)	8
Parts Bulletins	9
Technical Data (TED)	9
Tightening Torque (AZD)	9
Special Tools Catalog	9
Labor Times (KSD)	10
Reason for Policy	10
Procedures	10
Defect Code Number	11
Dealer Communication System (DCS) Message	12
Wiring Diagram (SSP)	12
Wiring Diagram Symbols	13
Wire Colors with Abbreviations	15
General Guidelines	16
Accessing BMW TIS	18
BMW Group CenterNet	19

Subject	Page
TIS Home Page	20
Notification System Messages	21
Service Information	22
What's New	23
Service Bulletins	24
General Search	25
Fault Code Search	25
Campaign Label Code Search	25
Campaign Defect Code Search	25
Bulletin Search	25
Date Search	25
What's New Search	25
Parts Bulletins	26
Operating Fluids	27
Legacy Information	28
Reference Information	29
Technical Training	30
TRI Bulletins	31
Videos	32
OBD	33
Technical Documentation	34
Materials Ordering	35
Tools and Equipment	36
Workshop Equipment	37
Special Tools	38
Top Links	39
Model Map	40
 AIR - Aftersales Information Research	 41
ISTA to AIR Transfer	41
AIR Search Function	43
Repair Instructions	43
AIR Watchlist	44

Information Resources

Model: All

Production: All

OBJECTIVES

After completion of this module you will be able to:

- List the different information sources located in the Technical Information System (TIS).
- Find Service Information Bulletins (SIB) quickly using the TIS website.
- Understand how information is organized in an SIB.
- Know the difference between a Service Action and a Recall.
- Identify the different media used to resource information materials.
- Demonstrate the ability to research all sources of technical information.
- Understand and use AIR.


Information Resources

Service Information Bulletins

The purpose of the Service Information Bulletin is to communicate with the BMW Center Service Department. The SIB's are written by the Quality and Service Engineering Department and are designed to update/inform technicians and after-sales personnel concerning:

- Current Product Quality Solutions
- Diagnostic Equipment and Special Tool Information
- Service Measures, Service Actions and Recalls
- Administrative Procedures

Service Information Layout



If a SIB must be revised the number stays the same, only the revision date will be changed. (In this case the revision date is September 2015).

The Content Section of an SIB is broken into several headings:

- Subject
- Model
- Situation
- Correction
- Procedure
- Parts Information and Warranty Information

Service Actions and Recalls

There are two major kinds of service bulletins:

- Service Actions (Campaigns)
- Recalls

Service Information Bulletins that contain Service Actions and Federal Safety and Emissions Recalls must be treated with greater urgency than a normal informational bulletin. Every effort should be made to ensure that vehicles that fall under a certain Service Action or Recall is modified or repaired as quickly as possible.

The Key Reader software (ISPA Next) or the DCS (Dealer Communication System) Vehicle History is used to determine if a particular vehicle is affected or not. DCS reports should be run by the service advisor or dispatcher each time a vehicle is in the workshop for maintenance or repairs. The DCS report will include the code number and the applicable SIB reference.

■ Service Action

Service Actions, commonly are situations that BMW has determined require a modification or repair to a selected group of vehicles.

These concerns are not limited to safety or emissions but may involve anything that may be a potential cause of dissatisfaction for the vehicle owner.

BMW takes this pro-active approach to ensure that their customers are not inconvenienced by future problems when a production, manufacturing or design problem has been discovered.

Service Actions therefore allow the owners of older vehicles to enjoy some of the production improvements made on later vehicles.

Customers should be made aware of Service Actions that are applicable to their vehicles when the vehicles is in the workshop for service so that the necessary arrangements can be made to perform the corrective measure.

Service Actions are covered by the BMW New Vehicle Limited Warranty or Emissions Warranty.

SI B 12 12 14
Engine Electrical Systems

July 2014
Technical Service

Service Action: Program Control Units (OBD)
PERFORM THE PROCEDURE OUTLINED IN THIS SERVICE INFORMATION ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THEY ARE IN THE SHOP FOR MAINTENANCE OR REPAIRS.

MODEL

F80 (M3 Sedan)	F82 (M4 Coupe)	With the S55 engine
----------------	----------------	---------------------

SI B 12 12 14

■ Recalls

Recalls apply only to systems which affect passenger safety or the ability of the vehicle to meet Federal (EPA) or State (e.g. CARB) emissions standards. The federal and state agencies which oversee Highway Safety and Emissions have the authority to issue standards and require manufacturers to recall vehicles which do not meet those standards.

Many recalls are initiated voluntarily. Through their own testing and information gathering systems, manufacturers sometimes discover that a defect exists or that standards have not been met. Under Federal law, the manufacturer is required to report these findings to the Government and take action to correct them.


Unlike a Service Action, a recall requires that every owner of a potentially affected vehicle be notified by mail as soon as possible. The letter must include a brief description of the defect and any potential hazards created by the problem. The names of vehicle owners are obtained from individual State DMV (department of motor vehicle) offices.

In addition to the letters, BMW centers must inform their customers about the recall when they appear on the ISPA Next or DCS report.

Vehicles that are out of the normal warranty period may still have the repairs made free of charge as long as the time period for the recall has not expired.

After the Service Action or Recall has been completed, apply a campaign label with the appropriate code number to the B-pillar of the vehicle.

The Dealer number should be embossed in the center of the label and the code number punched out. This will make it easier for future service personnel to determine if the work has already been performed.



Repair Instructions

Repair Instructions assist the technician to follow authorized repair procedures for disassembly, reassembly, maintenance, and troubleshooting for all models.

They include:

- Special Tool
- Tightening Torque
- Technical Data Information

The document number of the Repair Instructions uses the BMW Main group numbering system.

54- Main Group Number
12- Sub-Group Number
003- Work Operation

Description of instructions.

54 12 003

Adjusting glass slide/tilt sunroof lid



Special tools required:

- [00 9 315](#)
- [00 9 341](#)


Link to special tools required.



Necessary preliminary tasks:

- Remove [gaiter](#)

Link to additional operations required.



Ideal adjustment:

- Distance:
 - Distance A from glass slide/tilt sunroof lid (1) to roof (2) must be the same all round
 - A = all round 6.0 ± 0.5 mm
- Height:
 - Front - flush to 0.75 mm deeper
 - Rear - flush to 1.5 mm higher

Loosen left and right bolts (1).

Note:
To adjust, slacken screws (1) on left/right so that glass slide/tilt sunroof lid (2) can still just be adjusted.

Link to obtain tightening torque.

Tightening torque: [54 12 01AZ](#)


Vehicle Technical Diagnosis (FTD)

The purpose of the FTD is to inform center personnel about new systems, vehicles and production changes. The FTD does not address any product quality concerns but might include information on operating parameters. Often, FTD's apply to more than one vehicle. The intention is informational only and can be found in ISTA.

A benefit of an FTD is that it is usually written before the product is released so that personnel can become familiar with the new systems or technology on its way.

The layout of the Vehicle Technical Diagnosis is similar to an SIB. It includes:

- Title Block
- Introduction
- System Functions
- Operation



Parts Bulletins

The target audience of the Parts Bulletin System are Parts Managers and their employees, however the information can be useful as reference to a Technician.

The Parts Bulletins contain information concerning:

- Parts Ordering
- Parts Updates
- Vehicle Accessory Introductions
- Policies
- Warranty Information
- Parts Recalls and Campaigns

The layout is similar to that of the Service Information Bulletin. The Parts Bulletins are also arranged by the BMW Main Group numbering system. There are a few differences in groups 00 through 10, 80, 81 and 82. These groups are specific to issues concerning the Parts Department.

Technical Data (TED)

Technical data consists of specifications for systems and components.

Obtaining proper technical data is usually aided by accessing the technical data via a hotbox under repair instructions.

Tightening Torque (AZD)

Tightening torques can be obtained from the repair instructions main menu page. Obtaining proper tightening torques are usually aided by accessing the technical data via a hotbox under repair instructions.

Special Tools Catalog

Special tools are identified in the repair manual where their use is appropriate or required, however they may also be found in the special tools catalog on the under the TIS tab, Tools and Equipment.

As new tools are introduced they are published in Service Information Bulletins group 04. Later the tools can be found in the Tools and Equipment section of TIS or in the repair instructions.

Labor Times (KSD)

The KSD program is used to determine labor times allowed for repairs. The most current version of the KSD and the applicable Service Information Bulletins (SIB) are the only accepted sources of flat rate operations and times for warranty claims.

Reason for Policy

- To provide a unit of measure and a source for the determination of equitable repair times.
- To provide flat rate operation numbers to identify specific repairs.

Procedures


1. The BMW Flat Rate System is based upon flat rate units. Each flat rate unit is the equivalent of 6 minutes. The labor times for all warranty claims must be recorded in flat rate units. Effective with repairs performed on and after January 1, 2009, BMW NA will pay all labor based on an 10 FRU hour. Please refer to Service Information bulletin 01 07 08 for detailed information regarding this issue.
2. The BMW Flat Rate System is divided into numerical sections (groups) which generally correspond to the main component groups of the vehicle as identified in the service bulletins and KSD software supplied by BMW NA.
3. Main labor operations (as defined) are complete in themselves. All main labor operation numbers will end with 000 to 499 as the last three digits of the operation. A main operation includes all repair procedures to complete the task and an allowance for necessary ancillary tasks (e.g., visual inspection, lubrication with grease or oil, cleaning parts and assemblies). Refer to workshop manuals and service information bulletins for current and complete descriptions of work procedures. If you have two main labor operation numbers for a repair, overlapping labor times may exist and should be corrected before warranty claim submission. If doubt still exists after researching a labor operation number call the Warranty Department. The flat rate operations selected must be applicable to the model repaired.
4. Associated labor operations are used in conjunction with a main labor operation number. Associated labor operations consider work that has already begun and thus removes overlapping time that otherwise would occur should multiple main labor operations be combined. Associated labor operation numbers range from 500 to 999 for the last three digits of the operation number. Care should be used to select the correct associated labor operation based on the actual repair performed considering any overlapping labor times. In many of the repair groups there are multiple operations available for different repair combinations. Do not rely on memory; research the correct labor operation for the repair circumstances. If you are unsure after researching the labor operation, call the Warranty Department.

5. A plus (+) operation or plus code is a type of associated labor operation that must be applied in conjunction with performing multiple main labor repairs. One main labor operation should be used and any other main work performed should be coded with plus code operations. This removes the overlapping administrative time that otherwise would occur when utilizing multiple main labor operations. If a main operation is used during the vehicle visit for any type of repair charged to BMW NA and a plus (+) operation is available for any additional repairs, the plus (+) operation must be used.
6. The published time for all labor operation numbers cannot be changed during claim entry. The computer will pay the published flat rate value regardless of BMW center input. To claim less time because of recognized overlaps, use one of the special flat rate operation numbers for work time reimbursement (WPPM-5).
7. After researching the labor operation, if you believe the appropriate labor operation is missing or the time allowance is insufficient, report the situation to the Warranty Department. Complete a Flat Rate Survey Sheet or use your BMW center letter-head to describe the details of the situation. Be sure to include all of the applicable information (e.g., VIN for missing labor operations, labor operation number for discrepancies). Then fax this information to the Warranty Department.

Note: To ensure that only one main labor operation appears on any claim or group of claims from the same repair order, all open time/diagnostic time is to be considered as the main labor operation. All other operations on the same line or other lines of the repair order should be plus code operations if available (last three digits of the flat rate being 500 or higher).

Defect Code Number

Defect codes are necessary to specifically identify defects and provide quality control feedback. The KSD defect code catalog supplies this information in an easy to reference format that promotes accuracy and efficiency.



Dealer Communication System (DCS) Message

A DCS Message is generated by BMW if important information has to be released to the technicians or centers. This is the fastest method of communication from BMW to the dealerships. DCS messages are no longer posted on TIS. They are now only posted to DCSNet/DealerSpeed with all other DCS messages.

Publish Date: March 11, 2019 From: BMW Group University Expiration Date: March 29, 2019	DCSnet Message Important 
Subject: ST1856 General Vehicle Electronics 2018 Reference Manual Update	
To: BMW Service Managers, Shop Foremen, Technicians	
Subject: ST1856 General Vehicle Electronics 2018 Reference Manual Update	
Message: BMW Group University has updated the Technical Training Reference Manual, ST1856 General Vehicle Electronics 2018.	
The following new content consists of:	
Section 6 sub section 6.3 Retrofitting the ID Transmitter	
Section 10 Drive Recorder	
Please Note: The updated training material is available on the TIS website and DRIFT for download.	
















Wiring Diagram (SSP)

The wiring diagrams divide the vehicle electrical system into individual circuits. Components which interact with that circuit are shown on the same schematic.





In order to provide a standard for the way in which an SSP is written and read, there are general rules that apply. Components are drawn in such a way that their general layout and function are self-explanatory. They are arranged on the page so that the current path can be followed from **positive** (top) to **negative** (bottom).

In order to work effectively with the SSP, the technician has to understand the meaning of the symbols used to represent electrical components and connections.







Wiring Diagram Symbols



Wiring Diagram Symbols (cont.)

Permanent Magnet Motor 	Permanent Magnet Motor 	PMM (3 Phase) 
Brake Pad Sensor 	Hall Sensor 	Knock Sensor 
O₂ Sensor (before CAT) 	O₂ Sensor (after CAT) 	Pressure Sensor 
Wheel Speed Sensor 	Terminal Point 	Safety Battery Terminal 
Solenoid 	Solenoid Control Valve 	Solenoid Magnetic Clutch 

Wiring Diagram Symbols (cont.)



Wire Colors with Abbreviations

Today, most current wire diagrams/schematics now depict the color of the wires shown on the schematic.

Abbreviation	English	German
TR	Transparent	<i>Transparent</i>
WS	White	<i>Weiß</i>
VI	Purple	<i>Violett</i>
BL	Blue	<i>Blau</i>
BR	Brown	<i>Braun</i>
GE	Yellow	<i>Gelb</i>
GR	Gray	<i>Grau</i>
GN	Green	<i>Grün</i>
OR	Orange	<i>Orange</i>
RS	Pink	<i>Rosa</i>
RT	Red	<i>Rot</i>
SW	Black	<i>Schwarz</i>


General Guidelines

Wiring Diagram “**SSP-SP0000020123 LH Rear Seatback Adjustment**” will be used as an example.

To obtain more information on a component or signal, select any blue hotbox on the wiring diagram (additional information should appear to the right of the SSP, such as EBO, STA, PIB, etc.). It is also helpful to press the **Document** button, on the lower left of the navigation bar on ISTA, after selecting a component’s blue hotbox. This will show you all relevant SSP regarding the component you just selected.

Index	Explanation
1	Switches and relays are always shown in their rest position. (e.g. K135)
2	A component drawn in a dotted line indicates that only part of the component is shown. (e.g. A3)
3	A component drawn as a solid line indicates that all of that component is shown. (e.g. S10494)
4	The dotted line between connectors indicate that all the pins belong to that connector
5	Terminal operation is usually noted within a component box
6	Component designation is shown to the right of the box. (e.g. A3, K135, etc.)
7	Component name is shown under component designation. (e.g. Light module; Relay, rear compartment backrest)
8	Splice points are shown between components, noted by a connector number. (e.g. X10664, X1019, etc.)
9	Signal name, wire cross section and color are noted as a list to the right of the wire. Of note, the wire cross section is given in square millimeters (mm ²)

SSP-SP0000020123 LH Rear Seatback Adjustment




Accessing BMW TIS

To access technical information for BMW vehicles, you must first log on to dealerspeed.net using your web browser.



The screenshot shows the BMW NA Dealerspeed website. At the top, there is a header with "BMW NA" and "Dealerspeed" on the left, and the BMW logo and a globe icon on the right. Below the header, a message reads: "Welcome to the new Dealer site with access to both DCSnet and CenterNet. Please use your DCSnet id to log in." To the left of the login box is a large image of a winding road. To the right is a "Login" box with the text "Welcome" and "Please log in:". It contains two input fields: "Username: [text]" and "Password: [text]", followed by a "Login" button. At the bottom left, there is a "LEGAL NOTICE" section with small text.

Access to the BMW NA Dealerspeed website will be granted when a valid employee is entered in the dealer system (DEMS) by the center/technical service engineer.





The screenshot shows the BMW NA Dealerspeed website after login. The header is the same as the previous page. Below the header, there is a "Search" button and a "Logout" button. To the left of the destination box is a large image of a winding road. To the right is a "Choose your destination" box with three options: "CenterNet" (highlighted with a red box), "DCSnet (New)", and "DCSnet (Old)". Below this box is a "For assistance, please contact the BMW Group Dealer Systems Help Desk." section with the phone number "800-877-8144" and the "Hours of Help Desk Support" listed as "Monday - Friday 7:00 am - 9:00 pm ET" and "Saturday 8:00 am - 3:00 pm ET".

To access BMW TIS, select **CenterNet** from the destination navigation box.

BMW Group CenterNet

The screen that comes up next is the BMW Group CenterNet. This is the website dedicated to information pertaining to center operations.

Information on every aspect of the center is displayed here, from sales/marketing bulletins to new information on products available.



To access BMW TIS, select **TIS** from the top menu bar and then select **BMW** from the “drop down” menu.

TIS Home Page

The Technical Information System (TIS) home page includes the following major links to information on the site:

- TIS Notification System
- Service Information
- Reference Information
- Technical Documentation
- Materials Ordering
- Tools and Equipment
- Model Map

Home Model Map Contact

Technical Information System

Home **Service Information** Reference Information Technical Documentation Takata Recall Materials Ordering Tools and Equipment

Home

Notification System

Make this my Home Page

BMW USA

BMW Group Equipment Program

Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.

Google Search

What's New
30 Days

What's New Search Results [30 days]

Service Bulletin Information (New bulletins are highlighted)					
Bulletin Number	Type	Date	Subject	What's Changed	Series
<u>00 04 18</u>	SI	July 2018	2018 TECHNICIAN SURVEY FROM CARLISLE		All
<u>01 18 17</u>	SI	July 2018	N63T HIGH PRESSURE FUEL PUMP HDP LIMITED WARRANTY EXTENSION TO 10 YEARS/120,000	2013 Model Year vehicles were added and Warranty	F02, F07, F12, F13, F01, F06, F10
<u>01 02 18</u>	SI	July 2018	S63T HIGH-PRESSURE FUEL PUMPS (HDP): LIMITED WARRANTY EXTENSION TO 10 YEARS/120		F12, F13, F06, F10
<u>00 02 17</u>	SI	July 2018	2018 NEW VEHICLE PREPARATION AND MAINTENANCE REQUIREMENTS	M3 CS added and G30 diesel maintenance change	F34, F23, F12, G12, F30, F31, F32, F83, F36, G32, F82, F87, F33, F22, F90, F06, F80, G30
<u>65 13 16</u>	SI	June 2018	COMPONENT PROTECTION ACTIVE. HEADUNITS CANNOT BE SWAPPED BETWEEN VEHICLES FOR	Changed Title	F26, F34, F15, F23, F12, G12, F30, F31, F32, F36, F85, F86, F13, G01, G32, F33, I01, F22, F16, F25, G30
<u>34 04 18</u>	SI	July 2018	DELIVERY STOP & RECALL 18V-XXX: REAR BRAKES	Warranty information updated	G01, G02
<u>51 13 18</u>	SI	July 2018	LIN BUS FAULTS WITH EXTERIOR REARVIEW MIRROR GLASS DAMAGE		F39
<u>84 02 14</u>	SI	July 2018	CONNECTEDDRIVE/BMW ASSIST SYSTEM DIAGNOSIS INFORMATION	Model, Procedure and Information	F02, F26, F07, F34, F15, F23, F12, G12, F30, F31, F32, F83, F36, F85, F86, F13, G01, G32, F82, F87, F33, I01, I12, F22, F16, F25, F48, F90, F06, F80, F39, F10, G30
<u>32 05 18</u>	SI	July 2018	POWER STEERING ASSISTANCE UNAVAILABLE AFTER ENGINE	ISTA 4.12.3x has updated EPS SW	G01, G02

Notification System Messages

The first window that comes up once selecting TIS => BMW is the home page with the Notification System Messages.

Here, you will find information on the latest bulletins (last 30 days) and service measures (last 30 days). To distinguish between new and updated earlier bulletins, the new bulletins have been highlighted in yellow.

The information in this window is refreshed every 1.5 hours or less. This enables the technician to receive the most up to date information. Its a good habit to do a quick review of the bulletins on a daily basis, the more you know, the faster you may be able to diagnose and repair a vehicle.

Home Model Map Contact

Technical Information System

Home Service Information Reference Information Technical Documentation Takata Recall Materials Ordering Tools and Equipment

Home

Notification System

Make this my Home Page

BMW USA

BMW Group Equipment Program

Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.

Google Search

What's New
30 Days

What's New Search Results [30 days]

Service Bulletin Information (New bulletins are highlighted)

Bulletin Number	Type	Date	Subject	What's Changed	Series
<u>00 04 18</u>	SI	July 2018	2018 TECHNICIAN SURVEY FROM CARLISLE		All
<u>01 18 17</u>	SI	July 2018	N63T HIGH PRESSURE FUEL PUMP HDP LIMITED WARRANTY EXTENSION TO 10 YEARS/120,000	2013 Model Year vehicles were added and Warranty	F02, F07, F12, F13, F01, F06, F10
<u>01 02 18</u>	SI	July 2018	S63T HIGH-PRESSURE FUEL PUMPS (HDP): LIMITED WARRANTY EXTENSION TO 10 YEARS/120		F12, F13, F06, F10
<u>00 02 17</u>	SI	July 2018	2018 NEW VEHICLE PREPARATION AND MAINTENANCE REQUIREMENTS	M3 CS added and G30 diesel maintenance change	F34, F23, F12, G12, F30, F31, F32, F83, F36, G32, F82, F87, F33, F22, F90, F06, F80, G30
<u>05 13 16</u>	SI	June 2018	COMPONENT PROTECTION ACTIVE. HEADUNITS CANNOT BE SWAPPED BETWEEN VEHICLES FOR	Changed Title	F26, F34, F15, F23, F12, G12, F30, F31, F32, F36, F85, F86, F13, G01, G32, F33, I01, F22, F16, F25, G30
<u>34 04 18</u>	SI	July 2018	DELIVERY STOP & RECALL 18V-XXX: REAR BRAKES	Warranty information updated	G01, G02
<u>51 13 18</u>	SI	July 2018	LIN BUS FAULTS WITH EXTERIOR REARVIEW MIRROR GLASS DAMAGE		F39
<u>84 02 14</u>	SI	July 2018	CONNECTEDDRIVE/BMW ASSIST	Model Procedure	F02, F26, F07, F34, F15, F23, F12

Note: This screen should be minimized and not closed in order to allow the latest information to be displayed as soon as it is available.

Service Information

There are five sub-sections under Service Information. They are as follows:

- What's New - 30 Days
- Service Bulletins
- Parts Bulletins
- Operating Fluids
- Legacy Info

The screenshot shows the BMW Technical Information System (TIS) website. The 'Service Information' menu item is highlighted with a red circle. Below the navigation bar, the 'What's New 30 Days' section is displayed, showing a table of search results for service bulletins.

Bulletin Number	Type	Date	Subject	What's Changed	Series
00 04 18	SI	July 2018	2018 TECHNICIAN SURVEY FROM CARLISLE		All
01 18 17	SI	July 2018	N63T HIGH PRESSURE FUEL PUMP HDP LIMITED WARRANTY EXTENSION TO 10 YEARS/120,000	2013 Model Year vehicles were added and Warranty	F02, F07, F12, F13, F01, F06, F10
01 02 18	SI	July 2018	S63T HIGH-PRESSURE FUEL PUMPS (HDP): LIMITED WARRANTY EXTENSION TO 10 YEARS/120		F12, F13, F06, F10
00 02 17	SI	July 2018	2018 NEW VEHICLE PREPARATION AND MAINTENANCE REQUIREMENTS	M3 CS added and G30 diesel maintenance change	F34, F23, F12, G12, F30, F31, F32, F83, F36, G32, F82, F87, F33, F22, F90, F06, F80, G30
65 13 16	SI	June 2018	COMPONENT PROTECTION ACTIVE. HEADUNITS CANNOT BE SWAPPED BETWEEN VEHICLES FOR	Changed Title	F26, F34, F15, F23, F12, G12, F30, F31, F32, F36, F85, F86, F13, G01, G32, F33, I01, F22, F16, F25, G30
34 04 18	SI	July 2018	DELIVERY STOP & RECALL 18V-XXX: REAR BRAKES	Warranty information updated	G01, G02
51 13 18	SI	July 2018	LIN BUS FAULTS WITH EXTERIOR REARVIEW MIRROR GLASS DAMAGE		F39
84 02 14	SI	July 2018	CONNECTEDDRIVE/BMW ASSIST SYSTEM DIAGNOSIS INFORMATION	Model, Procedure and Information	F02, F26, F07, F34, F15, F23, F12, G12, F30, F31, F32, F83, F36, F85, F86, F13, G01, G32, F82, F87, F33, I01, I12, F22, F16, F25, F48, F90, F06, F80, F39, F10, G30
32 05 18	SI	July 2018	POWER STEERING ASSISTANCE UNAVAILABLE AFTER ENGINE	ISTA 4.12.3x has updated EPS SW	G01, G02

What's New

Entering **What's New** will reveal new information added to database in the last 30 days. Information includes:

- Service Bulletins
- Parts Bulletins
- Training Manual Updates
- Repair Manual Updates
- Operating Fluids Manual

Bulletin Number	Type	Date	Subject	What's Changed	Series
<u>00 04 18</u>	SI	July 2018	2018 TECHNICIAN SURVEY FROM CARLISLE		All
<u>01 18 17</u>	SI	July 2018	N63T HIGH PRESSURE FUEL PUMP HDP LIMITED WARRANTY EXTENSION TO 10 YEARS/120,000	2013 Model Year vehicles were added and Warranty	F02, F07, F12, F13, F01, F06, F10
<u>01 02 18</u>	SI	July 2018	S63T HIGH-PRESSURE FUEL PUMPS (HDP) LIMITED WARRANTY EXTENSION TO 10 YEARS/120		F12, F13, F06, F10
<u>00 02 17</u>	SI	July 2018	2018 NEW VEHICLE PREPARATION AND MAINTENANCE REQUIREMENTS	M3 CS added and G30 diesel maintenance change	F34, F23, F12, G12, F30, F31, F32, F83, F36, G32, F82, F87, F33, F22, F90, F06, F80, G30
<u>65 13 16</u>	SI	June 2018	COMPONENT PROTECTION ACTIVE. HEADUNITS CANNOT BE SWAPPED BETWEEN VEHICLES FOR	Changed Title	F26, F34, F15, F23, F12, G12, F30, F31, F32, F36, F85, F86, F13, G01, G32, F33, I01, F22, F16, F25, G30
<u>34 04 18</u>	SI	July 2018	DELIVERY STOP & RECALL 18V-XXX: REAR BRAKES	Warranty information updated	G01, G02
<u>51 13 18</u>	SI	July 2018	LIN BUS FAULTS WITH EXTERIOR REARVIEW MIRROR GLASS DAMAGE		F39
<u>84 02 14</u>	SI	July 2018	CONNECTED DRIVE/BMW ASSIST SYSTEM DIAGNOSIS INFORMATION	Model, Procedure and Information	F02, F26, F07, F34, F15, F23, F12, G12, F30, F31, F32, F83, F36, F85, F86, F13, G01, G32, F82, F87, F33, I01, I12, F22, F16, F25, F48, F90, F06, F80, F39, F10, G30
<u>32 05 18</u>	SI	July 2018	POWER STEERING ASSISTANCE UNAVAILABLE AFTER ENGINE	ISTA 4.12.3x has updated FDS SW	G01, G02



Detailed information is available by selecting the appropriate Bulletin or Update.

To select the desired bulletin, click on the underlined bulletin number (hyperlink).

Bulletin Number	Type	Date	Subject	What's Changed	Series
<u>00 04 18</u>	SI	July 2018	2018 TECHNICIAN SURVEY FROM CARLISLE		All
<u>01 18 17</u>	SI	July 2018	N63T HIGH PRESSURE FUEL PUMP HDP LIMITED WARRANTY EXTENSION TO 10 YEARS/120,000	2013 Model Year vehicles were added and Warranty	F02, F07, F12, F13, F01, F06, F10
<u>01 02 18</u>	SI	July 2018	S63T HIGH-PRESSURE FUEL PUMPS (HDP) LIMITED WARRANTY EXTENSION TO 10 YEARS/120		F12, F13, F06, F10
<u>00 02 17</u>	SI	July 2018	2018 NEW VEHICLE PREPARATION AND MAINTENANCE REQUIREMENTS	M3 CS added and G30 diesel maintenance change	F34, F23, F12, G12, F30, F31, F32, F83, F36, G32, F82, F87, F33, F22, F90, F06, F80, G30
<u>65 13 16</u>	SI	June 2018	COMPONENT PROTECTION ACTIVE. HEADUNITS CANNOT BE SWAPPED BETWEEN VEHICLES FOR	Changed Title	F26, F34, F15, F23, F12, G12, F30, F31, F32, F36, F85, F86, F13, G01, G32, F33, I01, F22, F16, F25, G30
<u>34 04 18</u>	SI	July 2018	DELIVERY STOP & RECALL 18V-XXX: REAR BRAKES	Warranty information updated	G01, G02
<u>51 13 18</u>	SI	July 2018	LIN BUS FAULTS WITH EXTERIOR REARVIEW MIRROR GLASS DAMAGE		F39
<u>84 02 14</u>	SI	July 2018	CONNECTED DRIVE/BMW ASSIST SYSTEM DIAGNOSIS INFORMATION	Model, Procedure and Information	F02, F26, F07, F34, F15, F23, F12, G12, F30, F31, F32, F83, F36, F85, F86, F13, G01, G32, F82, F87, F33, I01, I12, F22, F16, F25, F48, F90, F06, F80, F39, F10, G30
<u>32 05 18</u>	SI	July 2018	POWER STEERING ASSISTANCE UNAVAILABLE AFTER ENGINE	ISTA 4.12.3x has updated FDS SW	G01, G02

Entering Service Bulletins allow searching and selection of Service Bulletins.

- General Search
- Fault Code Search
- Campaign Label Code Search
- Campaign Defect Code Search
- Bulletin Search
- Date Search
- TCU Reactivate Lookup
- TCU Replace Lookup
- What's New



■ **General Search**

Used for looking up bulletins by group number and vehicle designation.

Entering information on all fields is not required and might even reduce the number of search results.

Entering the minimal amount of information in the fields increases the number of search results.

■ **Fault Code Search**

A bulletin search can also be performed by entering the fault code retrieved from a module during a fault interrogation.

Searches of partial fault code number are possible.

■ **Campaign Label Code Search**

A bulletin can be searched for by entering the defect code.

This can be helpful if the vehicle has a campaign label on the b-pillar or if the DCS message says to perform a defect code campaign instead of giving the bulletin number.

■ **Campaign Defect Code Search**

A bulletin can be searched for by selecting a defect code from the drop down menu provided for the technician.

■ **Bulletin Search**

If the exact number of the bulletin searched for is known, enter the information for the fields displayed.

Searches by partial SIB number are not possible.

■ **Date Search**

Date Search allows the search of bulletins and measures by a specific date range. All groups or individual groups may be searched.

■ **What's New Search**

This searches for Bulletins and Measures added in the last:

- 3 days
- 7 days
- 14 days
- 30 days

Parts Bulletins

To simplify bulletin searching, part bulletins now have a separate tab under the Service Information tab.

Parts Bulletins are searchable by:

- General Search
- Bulletin Search
- Whats new



The “General search” and “Bulletin search” tabs are used the same way as in the service bulletin section. The “What’s New” tab shows the most current part bulletins in the last 120 days.

Home Model Map Contact				
Technical Information System				
Home Service Information Reference Information Technical Documentation Materials Ordering Tools and Equipment				
Parts Bulletins What's New				
What's New - 120 Days				
Bulletin Number	Type	Date	Subject	
06 28 14	PBS	September 2014	TEC7W Rear Silencer with Exhaust Flap Return	
06 27 14	PBS	September 2014	TEC6W KLE Control Unit Return	
06 26 14	PBS	September 2014	TEC5W Swivel Joint Returns	
06 23 14	PBS	September 2014	TEC3W Leak Diagnosis Module Return	
06 22 14	PBS	August 2014	TEC2W Safety Box Return	
06 21 14	PBS	September 2014	TEC9V Fuel Tank / Level Sensor Returns	
06 20 14	PBS	August 2014	Special Parts Ordering Procedure	
06 19 14	PBS	August 2014	TEC8V Headliner Switch Module Return	
06 18 14	PBS	August 2014	TEC6V Vent Pipe Return	
06 17 14	PBS	August 2014	TEC5V Supporting Ring, Emblem button, Drive Unit Return	
06 16 14	PBS	July 2014	First Dangerous Goods Return	
06 15 14	PBS	June 2014	TEC4V Information Display Return	
06 14 14	PBS	June 2014	TEC3V Trim Panel Dashboard Return	
06 13 14	PBS	June 2014	TEC2V Supply Module Return	
06 12 14	PBS	June 2014	TEC1V Oxygen Sensor Return	
06 11 14	PBS	June 2014	TEC9U Thermostat Return	
06 04 14	PBS	May 2014	Parts Claims Policy	
06 03 14	PBS	May 2014	Center Returns Policy	
06 10 12	PBS	August 2014	NIMH and Li-Ion Battery Distribution and Recycling	
08 01 13	PBS	October 2013	R134a Refrigerant Gas: Updated Pricing Structure	
10 18 14	PBS	October 2014	F16 X6 New Service Parts List	
10 17 14	PBS	October 2014	F82 / F83 M4 New Service Parts List	

Operating Fluids

This feature allows the technician to find the proper operating fluids used in BMW vehicles by group number.



[Home](#)
[Model Map](#)
[Contact](#)

Technical Information System

[Home](#)
[Service Information](#)
[Reference Information](#)
[Technical Documentation](#)
[Takata Recall](#)
[Materials Ordering](#)
[Tools and Equipment](#)

[Home](#)
[Notification System](#)
[Make this my Home Page](#)
[BMW USA](#)
[BMW Group Equipment Program](#)

Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.

[Google Search](#)

Operating Fluids

General Search


Group Name	Manual Name	Group Name	Manual Name
Group 00	Maintenance and General Information	Group 32	Steering
Group 11	Engine	Group 33	Rear Axle
Group 13	Fuel System	Group 34	Brakes
Group 16	Fuel Supply Systems	Group 35	Pedals
Group 17	Radiator	Group 36	Wheels and Tires
Group 18	Exhaust System	Group 37	Integrated Suspension Systems
Group 21	Clutch	Group 41	Body
Group 23	Manual Transmission	Group 51	Body Equipment
Group 24	Automatic Transmission	Group 52	Seats
Group 25	Gear Shift Mechanism	Group 54	Sunroof and Convertible Top
Group 26	Drive Shaft	Group 61	Electrical System
Group 27	Transfer Case	Group 64	Air Conditioning and Heating
Group 28	Dual-Clutch Transmission	Group 97	Body Cavity Sealing and Undercoating
Group 31	Front Axle	Group 99	Car Care Products

Legacy Information

Under this section of the site you are able to look up information pertaining to older model vehicles.

The two categories that you can search by are as follows:

- Wiring Diagrams to E36
- Repair Manuals prior to E36



Reference Information

There are five sub-sections under Reference Information tab. They are as follows:

- Body & Paint
- Technical Training
- TRI Bulletins
- Videos
- OBD

Home Model Map Contact

Technical Information System

Home Service Information **Reference Information** Technical Documentation Takata Recall Mater

Welcome to the BMW Technical Information System

TIS Notification System

Bulletins

Bulletins added in the last 30 days

Bulletins are highlighted)

Bulletin Number	Type	Date	Subject	What's New
01 10 17	SI	July 2018	M57Y FRONT AND REAR EXHAUST NOX SENSORS: LIMITED WARRANTY EXTENSION TO 10 YEAR	Attachm Vehicle
00 04 18	SI	July 2018	2018 TECHNICIAN SURVEY FROM CARLISLE	
01 18 17	SI	July 2018	N63T HIGH PRESSURE FUEL PUMP HDP LIMITED WARRANTY EXTENSION TO 10 YEARS/120,000	2013 M vehicles and Wa
01 02 18	SI	July 2018	S63T HIGH-PRESSURE FUEL PUMPS (HDP): LIMITED WARRANTY EXTENSION TO 10 YEARS/120	
00 02 17	SI	July 2018	2018 NEW VEHICLE PREPARATION AND MAINTENANCE REQUIREMENTS	M3 CS : G30 die mainten change
65 13 16	SI	June 2018	COMPONENT PROTECTION ACTIVE. HEADUNITS CANNOT BE SWAPPED BETWEEN VEHICLES FOR	Change
34 04 18	SI	July 2018	DELIVERY STOP & RECALL 18V-XXX: REAR BRAKES	Warrant updated
51 13 18	SI	July 2018	LIN BUS FAULTS WITH EXTERIOR REARVIEW MIRROR GLASS DAMAGE	



Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.

Google Search

Technical Training

Allows access to technical training manuals online in portable document format (PDF).


This can be extremely helpful for the workshop environment, but also allows a technician access to the training material before actually attending a class.



Allows access to:

- General Search

The latest in technical reference information can be found by performing a general search in this tab.



Home Model Map Contact

Technical Information System

Home Service Information **Reference Information** Technical Documentation Takata Recall Materials Ordering Tools and Equipment

TRI Bulletins

General Search

Bulletin Number	Type	Date	Subject	Series
00_06_17	TRI	July 2017	Prefilled PuMAV TeileClearing Cases with Aftersales Information Research (AIR)	All
09_02_17	TRI	July 2017	PILOT PROGRAM: IRAP CONTROL UNIT RECOVERY	All
10_04_17	TRI	May 2018	TECHNICAL SERVICE VIDEOS AVAILABLE ON VIMEO	All
17_09_17	TRI	November 2017	SILICA PACKS INSIDE COOLANT EXPANSION TANKS	F22, F23, F30, F31, F32, F33, F34, F36, F39, F48, G01, G12, G30, G32, I12
32_04_17	TRI	May 2017	STEERING GEAR BOLTS PRESERVED WITH WAX	All
32_01_17	TRI	May 2017	STEERING GEAR BOLTS PRESERVED WITH WAX	F48
51_30_17	TRI	March 2017	VANITY MIRROR LIGHTING FUNCTIONAL CHANGE	F48
52_07_17	TRI	March 2017	EXECUTIVE LOUNGE SEATING FUNCTIONS LIMITED WHEN FRONTPASSENGER SEAT OCCUPIED	G12
61_38_17	TRI	October 2017	EOS TESTER AND CELL MODULE CHARGER SOFTWARE	F15, F30, F60, G12, I01, I12
61_33_17	TRI	August 2017	CELL MODULE REPLACEMENT: END OF SERVICE TESTER CODE 340	I01
61_32_17	TRI	April 2017	VEHICLE AT STANDSTILL WIPER SPEED RESET FUNCTION DISABLED	E89, F06, F07, F10, F10H, F12, F13, F15, F16, F22, F23, F25, F26, F30, F30H, F31, F32, F33, F34, F36, F48, F80, F82, F83, F85, F86, F87, G12, I01, I12
61_31_17	TRI	March 2018	THE HORN HONKS TWICE WHEN LOCKING VEHICLE WITH ENGINE RUNNING	F15, F16, F22, F23, F30, F30H, F31, F32, F33, F34, F36, F48

Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.


Google Search

Videos

Allows access to:

- General Search
- Date Search
- What's New

The latest repair information, technical specification, and product update videos can be found by performing a general search in this tab. Most videos found here are from service roundtables.



[Home](#)
[Model Map](#)
[Contact](#)

Technical Information System

[Home](#)
[Service Information](#)
[Reference Information](#)
[Technical Documentation](#)
[Takata Recall](#)
[Materials Ordering](#)
[Tools and Equipment](#)

[Home](#)
[Notification System](#)
[Make this my Home Page](#)
[BMW USA](#)
[BMW Group Equipment Program](#)

Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.

[Google Search](#)

Service Roundtable
General Search

General Search

Search for Video files by providing search criteria below and clicking the Submit button to retrieve results.

Main Groups:

[0] Maintenance and General Information
[1] Warranties
[2] Aftersales Development
[3] Technical Training
[4] Tools and Equipment
[5] Information Systems
[6] Service Roundtable
[7] Diagnosis
[8] Recall Management
[9] Programming/Coding
[10] TIS
[11] Engine
[12] Engine Electrical Systems
[13] Fuel Systems
[16] Fuel Supply Systems
[17] Cooling System
[18] Exhaust Systems
[21] Clutch
[22] Engine and gearbox suspension
[23] Manual Transmission

Series:

E12
E21
E23
E24
E28
E30
E31
E32
E34
E36
E38
E39
E46
E52
E53
E60
E61
E63
E64
E65

Subject/Title keyword: (use commas to separate multiple keywords)

[Submit](#)
[Reset](#)
[Cancel](#)

OBD

All OBD information is stored under this option.

The following menus are available:

- Model \$06 Interface data
- OBD II Overview and Drive Cycle
- OBD II Systems



OBD II Systems Information			
2016 2015 2014 2013 2012 2011 2010 2009 2008 2007 2006 2005 2004 2003 2002 2001 2000 1999 1998 1997 1996			
Engine Family (Test Group/DME)	Engine/Trans Type	Models	Production Dates
BX8-MEVD17.2.3-BN2020 Test Plan	B460 B58M	F22	2014,15,16,17
		F23	
		F30	
		F31	
		F32	
		F33	
		F34	
		F36	
		F48	
		G12	
		G30	
		I12	
D70BX7A0 Test Plan	N57T N47T	F02	2014-2017
		F10	
		F15	
		F25	
		F30	
MEVD1724-MEVD17.2.4-BN2020 Test Plan	N20	F10	2013,14,15,16,17
		F44	
		F46	
		F48	

Technical Documentation

There are three categories under Technical Documentation portal. They are as follows:

- Workshop Information
- Programming and Diagnostics
- General Reference

In this section of TIS, there are many helpful information and documents on workshop practices, service quality forms, ISTA, ISTA/P, Battery care, ISPI NEXT, Teileclearing, and Technical service. This new Technical Documentation page includes documents and links to projects and services used in your day to day business activities.

Materials Ordering

Several engineering information materials have special SD part numbers. These part numbers cannot be ordered via the conventional parts ordering system. They have to be ordered via DCSnet.

Examples of material ordered here are:

- Battery Charge Label
- QC1 Checklists
- Recall Labels

Material	Type	Unit	Subject	Material Catalog	Status
BATTERY CHARGE LABEL	Label	1000	BATTERY CHARGE LABEL	BATTERY CHARGE LABEL	Available
QC1 CHECKLISTS	Checklist	1000	QC1 CHECKLISTS	QC1 CHECKLISTS	Available
RECALL LABELS	Label	1000	RECALL LABELS	RECALL LABELS	Available

TIS Online Ordering Is Moving to DCSnet

MODEL

INFORMATION

Effective June 1, 2015, selected items that were available on TIS Online Ordering will **only** be available in DCSnet. This process will enhance your BMW Group ordering experience, as DCSnet.

Effective today, May 27, TIS Online Ordering is no longer available, as the inventory is being transferred to DCSnet.

If you need 2015 or 2016 QC 1 Checklists, please click on the attachments for a printable version.

The listing below includes the TIS item number, packaging, description, and the new DCSnet part number:

TIS Online Item #	Per	Desc
14-004	Pack of 10	2015
92-485	Pack of 25	2015
92-488	Pack of 25	2015
92-467	Pack of 25	2015
92-475	Pack of 25	2016
92-476	Pack of 25	2016
91-001	50 labels	Batter
91-002	50 labels	Batter
91-003	50 labels	Batter
91-004	50 labels	Batter
91-008	Pack of 25	2015
91-007	Each	Batter
92-084	Pad of 100	Emis
92-435	Roll of 50	Gene

Tools and Equipment

There are three categories in the Tools and Equipment portal. They are as follows:

- Workshop Equipment
- Special Tools
- Top Links

Quantity	Type	Date	Subject	Work Change	Serial
01.01.18	50	October 2018	Proton Connector Failure with CG-7	Connector and Procedure	001, 001, 002, 003, 004, 005, 006, 007, 008, 009, 010, 011, 012, 013, 014, 015, 016, 017, 018, 019, 020, 021, 022, 023, 024, 025, 026, 027, 028, 029, 030, 031, 032, 033, 034, 035, 036, 037, 038, 039, 040, 041, 042, 043, 044, 045, 046, 047, 048, 049, 050, 051, 052, 053, 054, 055, 056, 057, 058, 059, 060, 061, 062, 063, 064, 065, 066, 067, 068, 069, 070, 071, 072, 073, 074, 075, 076, 077, 078, 079, 080, 081, 082, 083, 084, 085, 086, 087, 088, 089, 090, 091, 092, 093, 094, 095, 096, 097, 098, 099, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

Home Model Map Contact

Technical Information System

Home Service Information Reference Information Technical Documentation Takata Recall Materials Ordering **Tools and Equipment**

Home

Notification System

Make this my Home Page

BMW USA

BMW Group Equipment Program

Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.

Google Search

Tools and Equipment

Welcome to the Special Tools and Workshop Equipment Information Portal

New KDS Alignment Software - 6/2018

New End of Service tester software V4.6 - 3/2018

Workshop Equipment

KDS Alignment Software 6/2018

KDS Operation Manual

KDS Software Alert

EOS Tester Software Update 3/2018

Tire Pressure Monitor Sensor Generations

5X112 Lug Bolt Configuration

EQUIPMENT MANUALS

Gearbox Support Adapter

Hunter TCA34 Tire Changer Manual

Power Probe Brake Bleeder Manual

Hunter GSP972205 Manual

Special Tools

[BMW Group Shared Tools](#)

Search by 6 digit number

Search by 11 digit number

Search by Description

Search by Group

Complete Tool Report

Autoship Tool Report

WSK Engine Crane Parts

Special Tool Parts Warranty

Tool Problem Information

Required Special Tools List

BMW Workshop Equipment List

DMTL Smoke Adapter

Top Links

DME Break-Out Box Overlay ID

Deutronic Charger Repair Special - 3/2018

Approved Battery Chargers

Order TKR Spare Parts

Repair Multicharger 1500

Spare Parts Ordering: DEF Extraction/Fill Unit and Engine Coolant Vacuum Charger System



TKR Hydraulic Bearing Tool Application Chart

TKR Hydraulic Tool Part Numbers

BMW Workshop Equipment Maintenance List


Workshop Equipment

Allows access to instructions and software for the BMW Hunter alignment machine and various other BMW workshop equipment manuals.




Allows you to search for special tool information by selecting one of the following:

- Search by 6-Digit Part Number
- Search by 11-Digit Part Number
- Search by Description
- Search by Group
- Complete Tool Report
- Autoshop Tool Report




Special tool warranty information and FAQs are also found here.



Note: Usually the most reliable and direct method of knowing what special tools are needed should be obtained from the repair instructions.

Top Links

Quick links to popular information regarding BMW shop equipment.



SI B04 30 11
Tools and Equipment

September 2013
Technical Service

This Service Information bulletin supersedes SI B04 30 11 dated December 2011.

NEW designates changes to this revision

SUBJECT


TKR Spare Parts Ordering

MODEL

All

INFORMATION

Spare Parts (non-warranty) for TKR tools (listed below) are now available for purchase directly from the TKR website.



Hydraulic Wheel Bearing Tool
P/N 81 34 2 160 009
[SI B04 13 10](#)

Allows the technician to find information on vehicle series, engine, and model year.

The model map is based on digits 4-7 of the VIN. These numbers determine the breaks in major changes during production.


[illegible]

Home

Model Map

Contact

Technical Information System



BMW

BMW

Home

Service Information

Reference Information

Technical Documentation

Materials Ordering

Tools and Equipment

Home

Notification System

Make this my Home Page

BMW USA

Please Note: Internet Explorer users may have to turn on Compatibility View for correct display of service bulletins.

Please select a Model and/or a Series and/or an Engine and/or a Year and click the Submit button to view a list of all applicable BMW or MINI vehicles that match your selections. The data available in the dropdowns will be filtered as you make selections to prevent invalid combinations.

Click the Reset button to re-initialize the form if you wish to make new selections.

Select Model

Select Series

Select Engine

Select Year


Submit

Reset


AIR - Aftersales Information Research

With the migration from 3g to ISPI Next came along a new tool integrating various service data into a single system, known as AIR (Aftersales Information Research). This new tool provides easier access to service data like repair instructions, labor times, bulletins, and parts. AIR also has a watchlist feature that allows for information sharing with the technicians and warranty administrator. With AIR, the technician can be more productive and efficient by enabling the technician to find all the needed service data in one system.



ISTA to AIR Transfer



After reading the fault memory, technicians can search for SIB's by pressing the "SIBs" button, which will transfer you directly to AIR.



After calculating a test plan and obtaining a diagnosis code, press “Repair Overviews” and this will transfer the technician directly to AIR.



AIR Search Function

When in AIR, the gray header at the top of the page has a search box where technicians or workshop users can search for various types of information by using their VIN.

The screenshot shows the AIR search function interface. At the top, there is a search bar with a red box around it. Below the search bar, there are tabs for various information types: Service information, Flat Rate Units, Packages, Defects, Repair overview (parts...), Parts, Repair instructions, Tightening torques, Technical data, and MED. The left sidebar contains a list of vehicle-related links. The main content area displays the vehicle details for a BMW 335d, 225kW, with a VIN of W003094. A car image is shown, along with technical specifications like Development code (E90), Color (BLACK 2), Actual integration level (E900-12-03-202), and Start of warranty (June 18, 2009). A warning icon indicates that there are technical campaigns for this vehicle. Below this, a table lists technical campaigns with columns for Status, Campaign number, Description, Details, Linked information, and Reservation.

Status	Campaign num...	Description	Details	Linked information	Reservation
Open	10061660400	Repair of Repair BMW Motor Wing Local campaign number: 17V-576		0 defects	

Repair Instructions

Within this page, technicians can retrieve Flat Rates/Labor times, parts information, and Repair Overview for the applicable Repair Instruction.

The screenshot shows the AIR repair instructions interface. At the top, there is a search bar with a red box around it. Below the search bar, there are tabs for various information types: Service information, Flat Rate Units, Packages, Defects, Repair overview (parts...), Parts, Repair instructions, Tightening torques, Technical data, and MED. The left sidebar contains a list of vehicle-related links. The main content area displays the repair instructions for replacing a battery positive lead. It includes a warning icon, an information icon, and a list of necessary preliminary tasks: Remove battery, Remove fuel tank, Partially remove front right wheel arch trim, and Remove cover from electronics box. A photo shows the battery positive lead being replaced. The instructions are for a BMW 335d, 225kW, with a VIN of W003094.

Repair instruction

Replacing battery positive lead (from luggage compartment connector to engine bulkhead connector) (66 FR 0)

61 12 001 (FR 0) - 61 12 001 (FR 0) - 61 12 001 (FR 0)

Important!
Read and comply with notes on handling wiring harnesses and cables.

Necessary preliminary tasks:

- Remove battery
- Remove fuel tank
- Partially remove front right wheel arch trim
- Remove cover from electronics box

Work is shown on the E90 N204 by way of example. There may be differences in detail in the case of other vehicle models.

Undo covers (1) and release nuts underneath. Tightening torque 61 12 042.
Disconnect battery positive lead (2).

AIR Watchlist

The AIR Watchlist allows for sharing information among all of the workshop team members using AIR.

Technicians can add Flat Rates, Repair Overviews, Repair Instructions, and SIB's to the Basket. Notes can also be saved by inserting text within the Watchlist.

The contents of the Watchlist can be viewed and edited by other AIR users in the dealership. By the technician adding information about a repair to the Watchlist, it can help the warranty administrator book the repair more efficiently.

The screenshot shows the 'Watchlist BMW 335xi' window. At the top, it displays 'VIN: ED63934', 'Entered: 7/9/18 8:50:21 PM', 'Watched: 3', 'Order number: -', and 'Dealer: 0001214'. Below the header is a toolbar with icons for checkmark, list, trash, edit, print, and share. A 'Free search' field is present. The main content area is divided into sections: 'Notes' with a text input field (2000 Characters left), 'Service Information Bulletins (1)' with a checkbox for 'B64 07 17 RECALL 17V-676 BLOWER MOTOR WIRING', 'Flat Rate Units (1)' with a checkbox for 'General vehicle electrical system / Positive battery cable', and 'Technical documents (1)' with a checkbox for '61 12 004 Replacing battery positive lead (from luggage compartment connector to engine bulkhead connector)'. The technical document entry includes the text 'Repair instruction IREP REP RAE9281 6112004 V.1'.