CUSTOMER #: 261535

ALEXANDER JEFFERY COLLINS

INVOICE # 455538

INVOICE



FOR NOW. FOREVER.

BURNABY, BC V5B 2I HOME: 604-339-3673	CONT: 604-	0.50	PAGE 1	5750 Lougheed Hwy. Burnaby, B.C. V5B 2Z9 Phone: (604) 294-6525 www.coastalford.com 3 0 TREVOR HUTCHINSON				
BUS: 604-628-8881 COLOUR YEAR	MAKE/MODEL		SER	VICE ADVISOR:	LICENSE		METER IN	TAG
			de la viena de la Cala	***	COLINGE			
	D EXPLORE			K8D83HGA90287		The second secon	1/9601	
IN SVC. DATE PROD. DATE	WARR, EXP.	ESTIMATED PRO	MISE TIME	PO NO.		PAYMENT	INV. D	ATE
31JAN17 IS		15:00 0	9NOV17		0.00	CASH	10NOV	17
	NVOICE PRINTEL			LD-STK: 7EXA90				
		TRN: A	T 2) RCI	L36 11) FMPP 3	6/61 NORM	MAL \$0 6	5M/12K	
11:18 09NOV17 16:					T T C	\	700	T 7 T
LINE OPCODE TECH TALE A CHECK ENGINE LIC			ומ מגממ	IDED DO COLL	LIST		ET TO	TAL
				DENT RELAQTED	,	CUKIS		
COLLISION-			R					
13 CHECK ENG			. 2					
31 1	BROWN, MICE C 1.20		: 4					
32	C 0.00							
	1.20					139.	95 139	.95
4 KT13648			1.90			.60		
1 8370-43			DING E	DOM DAM	3.90	3.5	90 3	.90
60 REPAIR IN CHEWING	DECTOR AND	O COTP MT	RING F.	ROM RAT				
32	C 2.5	0	* 5 5	- 1011		324.	88 324	.88
86 ENGINE SH			PARTS			·		
					4 4 4			
PARTS: 11.50		504.78	OTHER	0.00				.95
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAM ON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ********* ERS FRT T	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ********** 'IRE FLAT-	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O NG CHE SIBLE C BE MORE REPAI SHAMPO	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, HEWED WIRING, KED WIRING AS O'D AS REQUIRES	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I REQUIRE RED.	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT CD, CLEA	516 AS R S ING AND	
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAMON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV 52.00 REPAIR	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******** ERS FRT I FLAT TIR	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ********* IRE FLAT- E AND RE-	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O NG CHE SIBLE C BE MORE REPAI SHAMPO	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, HEWED WIRING, KED WIRING AS O'D AS REQUIRES	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I REQUIRE RED.	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT CD, CLEA	AS R S ING AND RED	9.95
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAMON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******** ERS FRT T C 0.5	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ********* IRE FLAT- E AND RE-	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O NG CHE SIBLE C BE MORE REPAI SHAMPO	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, HEWED WIRING, KED WIRING AS O'D AS REQUIRES	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I RED. ************************************	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT D, CLEA	S ING AND RED	9.95 7.28
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAP ON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST *** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T FLAT TIR C 0.5 RE PLUG LABOR:	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** IRE FLAT- E AND RE- 10 29.95	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, CHEWED WIRING, WIRING DAMAG RED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I RED. ********* 7.28 TOTAL I	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT D, CLEA *** 29. 3 7. LINE B:	S ING AND RED	9.95 7.28 7.23
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAMON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T FLAT TIR C 0.5 RE PLUG LABOR:	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** IRE FLAT- E AND RE- 10 29.95	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, CHEWED WIRING, WIRING DAMAG RED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I RED. ********* 7.28 TOTAL I	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT D, CLEA *** 29. 3 7. LINE B: BIPTION	S ING AND RED	9.95 7.28
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAMON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI PARTS: 7.28	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T FLAT TIR C 0.5 RE PLUG LABOR:	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** IRE FLAT- E AND RE- 10 29.95	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, CHEWED WIRING, WIRING DAMAG RED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I RED. ********* 7.28 TOTAL I	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT CD, CLEA *** 29. 3 7. LINE B: RIPTION MOUNT	S ING AND RED	9.95 7.28 7.23
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAP ON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T FLAT TIR C 0.5 RE PLUG LABOR:	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** IRE FLAT- E AND RE- 10 29.95	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, CHEWED WIRING, WIRING DAMAG RED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I RED. ********* 7.28 TOTAL I	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT CD, CLEA *** 29. INE B: RIPTION MOUNT OUNT	S ING AND RED	9.95 7.28 7.23
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAP ON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI PARTS: 7.28	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T FLAT TIR C 0.5 RE PLUG LABOR:	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** IRE FLAT- E AND RE- 10 29.95	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA F ENGINE. REN WED THROUGH, CHEWED WIRING, WIRING DAMAG RED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE E THAT I RED. ********* 7.28 TOTAL I	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT CD, CLEA *** 29. 3 7. LINE B: RIPTION MOUNT OUNT FEE	S ING AND RED	9.95 7.28 7.23
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAMON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI PARTS: 7.28	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T FLAT TIR C 0.5 RE PLUG LABOR:	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** TECH 32>> ENGINE ******** TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TRE FLAT- E AND RE- TO 29.95 Ask us if you Privacy Policy, their data procaccessible to security author transaction inforcanda, Limite transaction, privacy policy, author transaction, privacy author Tansaction, privacy author Tansaction, privacy policy, displayed author Tansaction inforcanda, Limite transaction, privacy policy, author Tensaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy pr	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA FENGINE. REN WED THROUGH, HEWED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE ENGINE EREQUIRE RED. ******** 7.28 TOTAL I OUT ABOUR A DISPOSAL OUT COURT COU	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT D, CLEA *** 29. INE B: RIPTION MOUNT FEE MOUNT	S ING AND RED	9.95 7.28 7.23
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAP ON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST *** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI PARTS: 7.28 "At Your So TWO LOCATIONS TO SERVE Monday - Thus	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******** ERS FRT T FLAT TIR C 0.5 RE PLUG LABOR: VOU BUTTER rsday	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** TECH 32>> ENGINE ******** TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TRE FLAT- E AND RE- TO 29.95 Ask us if you Privacy Policy, their data procaccessible to security author transaction inforcanda, Limite transaction, privacy policy, author transaction, privacy author Tansaction, privacy author Tansaction, privacy policy, displayed author Tansaction inforcanda, Limite transaction, privacy policy, author Tensaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy pr	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA FENGINE. REN WED THROUGH, HEWED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE ENGINE EREQUIRE RED. ******** 7.28 TOTAL I OUT ABOUR A DISPOSAL OUT COURT COU	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT D, CLEA *** 29. INE B: RIPTION MOUNT FEE MOUNT	S ING AND RED	9.95 7.28 7.23
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAP ON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST **** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI PARTS: 7.28 "At Your So TWO LOCATIONS TO SERVE Monday - Thui 7:30 a.m. to 6:3	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T C 0.5 RE PLUG LABOR: YOU BUTTER rsday 30 p.m.	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** TECH 32>> ENGINE ******** TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TRE FLAT- E AND RE- TO 29.95 Ask us if you Privacy Policy, their data procaccessible to security author transaction inforcanda, Limite transaction, privacy policy, author transaction, privacy author Tansaction, privacy author Tansaction, privacy policy, displayed author Tansaction inforcanda, Limite transaction, privacy policy, author Tensaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy pr	OTHER 32>> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE SIBLE C SIBLE	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA FENGINE. REN WED THROUGH, HEWED WIRING AS O'D AS REQUIR ************************************	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE ENGINE EREQUIRE RED. ******** 7.28 TOTAL I OUT ABOUR A DISPOSAL OUT COURT COU	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT D, CLEA *** 29. INE B: RIPTION MOUNT FEE MOUNT	S ING AND RED	9.95 7.28 7.23
PARTS: 11.50 9601 TECH 31>> 1 HRS / ENGINE SHAP ON. VEHICLE INSP BAD MISS-FIRE. I #4 INJECTOR FAUL CYLINDER #4 IS M ENGINE COVER. FO TO INSPECT. FOUN CHEWED. REQUIRES SHAMPOO, THEN RE VISIBLE AT THIS CODES AND RETEST *** B REPORT WHY DRIV 52.00 REPAIR 62 1 PC-2 TI PARTS: 7.28 "At Your So TWO LOCATIONS TO SERVE Monday - Thus	LABOR: .2HR DIAG MPOO 0.4 ECTED AND DS TEST P TS AND MI ISS-FIRIN UND RODEN D INJECTO REPAIR O -TEST. TH TIME. // ED NOW OK ******* ERS FRT T C 0.5 RE PLUG LABOR: YOU BETTER rsday Roday rday	504.78 // TECH HR // 31> FOUND DU ERFORMED SS-FIRE G BADLY. T NEST ON R #4 WIRI F ALL VIS ERE MAY E TECH 32>> ENGINE ******** TECH 32>> ENGINE ******** TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TECH 32>> ENGINE ******* TRE FLAT- E AND RE- TO 29.95 Ask us if you Privacy Policy, their data procaccessible to security author transaction inforcanda, Limite transaction, privacy policy, author transaction, privacy author Tansaction, privacy author Tansaction, privacy policy, displayed author Tansaction inforcanda, Limite transaction, privacy policy, author Tensaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy policy, author Tensaction inforcanda, Limite transaction, privacy privacy policy, author Tensaction inforcanda, Limite transaction, privacy pr	OTHER 32 >> W > CONC RING D AND FO PERFOR INSPEC I TOP O ING CHE BELE CO BE MORE REPAI SHAMPO ******TOWE BALANO OTHER Would lill including cussing in U.S. law rities. We ormation to d to enabl ovide you otive relate rise which yapplicable ford.ca) if J.S. data st keting or se	IRING HARNESS ERN OF CHECK RIVE INTO SHO UND CODES REI MED POWER BAI TED ENGINE BA FENGINE REN WED THROUGH, CHEWED WIRING AS OO'D AS REQUIR THE STANDARD THE STANDARD THE STANDARD THE STANDARD THE STANDARD THE STANDARD TO THE STANDARD	REPAIR ENGINE L P THAT E ATED TO ANCE AND AY AND RE MOVED SOM AND COIL ENGINE ENGINE EREQUIRE RED. ******** 7.28 TOTAL I OUT ABOUR A DISPOSAL OUT COURT COU	INE A: 2.5 IGHT IS NGINE H CYLINDE FOUND MOVED E DEBRI #4 WIR VACUUM S NOT D, CLEA *** 29. 3 7. INE B: RIPTION MOUNT FEE MOUNT RGES ARGES RANCE	S ING AND RED	9.95 7.28 7.23

CUSTOMER #: 261535

BURNABY, BC V5B 2L7

6705 WINCH ST

ALEXANDER JEFFERY COLLINS

455538

INVOICE



FOR NOW. FOREVER.

5750 Lougheed Hwy. Burnaby, B.C. V5B 2Z9 Phone: (604) 294-6525

PAGE 2

				SER	VICE ADVISOR:	30 TREV			
BUS: 604-628-8881 CELL:604-808-9403 COLOUR YEAR MAKE/MODEL				VIN	LICENSE	ODOMETER IN		TAG	
GRAY 17		FORD EXPLORER			1FM5K8D83HGA90287		9601/9601		T4523
PROD.	DATE	WARR, EXP.	ESTIMATED PRO	MISE TIME	PO NO.		PAYMENT	INV. E	DATE
LJAN17 IS 15:00		15:00 09	09NOV17		0.00	CASH	10NOV17		
ED	11	VVOICE PRINTE							
	28-88 YEAR 17 PROD.	28-8881 YEAR 17 FOR PROD. DATE	YEAR MAKE/MODEL 17 FORD EXPLORE PROD. DATE WARR. EXP.	17 FORD EXPLORER PROD. DATE WARR, EXP. ESTIMATED PRO 15:00 09 INVOICE PRINTED INFORMA	YEAR MAKE/MODEL 17 FORD EXPLORER 1FM5F PROD. DATE WARR. EXP. ESTIMATED PROMISE TIME 15:00 09NOV17 INVOICE PRINTED INFORMATION:SOI	28-881 CELL: 604-808-9403 SERVICE ADVISOR:	28-8881 CELL:604-808-9403 SERVICE ADVISOR: 30 TREVICE ADVISOR:	28-8881 CELL:604-808-9403 SERVICE ADVISOR: 30 TREVOR HUTCH: YEAR	28-8881 CELL:604-808-9403 SERVICE ADVISOR: 30 TREVOR HUTCHINSON

11:18 09NOV17 16:30 10NOV17

LINE OPCODE TECH TYPE HOURS

LIST NET TOTAL

9601 FOUND SCREW IN LF TIRE. INFLATED TIRE AND DROVE INTO SHOP AND PERFORMED TIRE REPAIR.

ECO FEES, ENVIRONMENTAL LEVY'S & SHOP SUPPLIES

52.40

MOTOR CO. IN THE NEXT FEW DAYS. THE

* INFORMATION FROM THE SURVEY IS VERY

* IMPORTANT TO US. IF FOR ANY REASON YOU *

* CANNOT RESPOND AS "COMPLETELY SATISFIED" *

* PLEASE CONTACT DAVE COOK AT 604-294-6525 *



GOODS AND SERVICES TAX PROVINCIAL SALES TAX

(#:

R899766141)

30.30

678.62

"At Your Service"

TWO LOCATIONS TO SERVE YOU BETTER!

Monday - Thursday 7:30 a.m. to 6:30 p.m. Friday - Saturday 7:30 a.m. to 6:00 p.m. Ask us if you would like information about our Privacy Policy, including our service providers and their data processing in the U.S., which may be accessible to U.S. law enforcement and national security authorities. We provide this personal and transaction information to Ford Motor Company of Canada, Limited to enable Ford to administer your transaction, provide you with requested services, improve automotive related products and services by conducting customer surveys, and provide you with marketing material which may be of interest to you, as permitted by applicable laws. For the Ford Privacy Policy (www.ford.ca) including use of service providers and U.S. data storage or if you do not want to receive marketing or survey materials from Ford please call

DESCRIPTION TOTALS LABOUR AMOUNT 534.73 18.78 PARTS AMOUNT DISPOSAL FEE 0.00 SUBLET AMOUNT 0.00 SHOP CHARGES 52.40 TOTAL CHARGES 605.91 0.00 LESS INSURANCE GST/PST 72.71 PLEASE PAY

THIS AMOUNT

GST # 899766141

COASTAL FORD BURNABY 5750 LOUGHEED HWY BURNABY BC V5B 2Z9 (604) 294-6525

DEBIT SALE

Clerk #: 000035 Brad G

REF#: 00000005

Batch * 197 11/14/17

SEQ: 197001001005

Invoice #: 455538

12:12:26

APPR CODE: 160791

DEBIT/CHEQUING *************4085C

AMOUNT

\$678.62

00 - APPROVED - 001

INTERAC AID: A0000002771010 TVR: 02 00 00 80 00 TSI: F8 00

> Thank You Please Come Again

CUSTOMER COPY