



New Review - Home Quality Review

| Builder        | DRB Group                  |
|----------------|----------------------------|
| Region         | North Carolina             |
| Division       | Raleigh                    |
| Community      | Essex Village TH (NC)(RAL) |
| Lot            | 00.0140                    |
| Street Address | 218 Alberta Drive          |
| Field Manager  | Michael Joyner             |
|                | Matthew Wing               |
| Reviewer       | Bill Beard                 |
| Date           | 6/17/2026                  |
| Type           | New Review                 |
| Product Type   | Townhouse                  |

| Score                         | 93.75% |
|-------------------------------|--------|
| Second Look, Paint & Drywall? | No     |
| Possible Points               | 100.00 |
| Adj. Possible Points          | 100.00 |
| Tic Marks                     | 8      |
| # of Items                    | 21     |
| Customer Exceptions           | 0      |
| Weather Exceptions            | 0      |
| Division Exceptions           | 0      |
| Builder Items                 | 0      |
| No Action Items               | 0      |

Reschedules

Tic Mark Items

| Item          | Tic Marks | Description | Points |
|---------------|-----------|-------------|--------|
| Minor Drywall | 1         |             | 0.25   |
| Minor Paint   | 4         |             | 0.5    |
| Minor Clean   | 3         |             | 0.25   |

Items

| Room            | Trade                 | Item                                     | Description                                                                     | Points | Initials |  |
|-----------------|-----------------------|------------------------------------------|---------------------------------------------------------------------------------|--------|----------|--|
| Bath - Hall     | Interior_Trim         | 1560 - Out of plumb/square               | Shoe mould at right side of vanity not square with floor                        | 0.25   |          |  |
| Bath - Owner's  | Ceramic               | 1220 - Tile Installation Issue           | Corners and bottom edges of tile not sealed in shower                           | 0.25   |          |  |
| Bath - Powder   | Plumbing              | 721 - Pedastal Sink Water Lines Visible  | Water line visible on left side of pedestal sink                                | 0.25   |          |  |
| Bedroom 1       | Drywall               | 1400 - Miscellaneous                     | Left front bedroom, drywall return above front window uneven                    | 0.25   |          |  |
| Exterior        | Concrete_Flatwork     | 520 - Stain                              | Stain on patio in middle of slab                                                | 0.25   |          |  |
| Exterior        | Concrete_Flatwork     | 500D - Damage                            | Looking at home right edge of patio chipped near back wall                      | 0.25   |          |  |
| Exterior        | Concrete_Flatwork     | 500D - Damage                            | Corner of patio broken behind hvac unit                                         | 0.25   |          |  |
| Exterior        | Doors                 | 50007 - Exterior Doors Missing Schlaggle | Schlagel pads missing at front door                                             | 0.25   |          |  |
| Exterior        | Doors                 | 50000D - Damage                          | Paint on all hinges of back door                                                | 0.25   |          |  |
| Exterior        | Doors                 | 50007 - Exterior Doors Missing Schlaggle | Schlagel pads missing at back door                                              | 0.25   |          |  |
| Exterior        | Exterior_Appointments | 12000 - Miscellaneous                    | Gap between column and back side bottom trim                                    | 0.25   |          |  |
| Exterior        | Exterior_Trim         | 20070 - Tamished Threshold               | Back door threshold tarnished                                                   | 0.25   |          |  |
| Exterior        | Exterior_Trim         | 20000D - Damage                          | Jamb at back door chipped below strike plate                                    | 0.25   |          |  |
| Exterior        | Siding                | 4000D - Damage                           | Siding above and on each side of service disconnect stained                     | 0.25   |          |  |
| Family Room     | Interior_Trim         | 1560 - Out of plumb/square               | Shoe mould on wall that is common with refrigerator space not square with floor | 0.25   |          |  |
| Garage          | Concrete_Flatwork     | 520 - Stain                              | Concrete splatter and paint on right side of slab at entrance                   | 0.25   |          |  |
| Garage          | Concrete_Flatwork     | 520 - Stain                              | Orange stains on slab in middle of rear section                                 | 0.25   |          |  |
| Kitchen/Dinette | Electric              | 810 - Crooked Outlet/Switch              | On family room end of island, gap between receptacle plate and island panel     | 0.25   |          |  |
| Kitchen/Dinette | Interior_Trim         | 1560 - Out of plumb/square               | Shoe mould on end of island near back door not square with floor                | 0.25   |          |  |
| Stairs/Hall     | Interior_Trim         | 1520 - Miscut                            | Ripped trim on side of attic stairs panel is uneven in width                    | 0.25   |          |  |
| Utility Room    | Doors                 | 50000D - Damage                          | Top of door dented                                                              | 0.25   |          |  |

Scored Photos




Bath - Hall  
1560 - Out of plumb/square  
Shoe mould at right side of vanity not square with floor



Bath - Owner's  
1220 - Tile Installation Issue  
Comers and bottom edges of tile not sealed in shower




Bath - Powder  
721 - Pedastal Sink Water Lines Visible  
Water line visible on left side of pedestal sink




Bedroom 1  
1400 - Miscellaneous  
Left front bedroom, drywall return above front window uneven



Exterior  
12000 - Miscellaneous  
Gap between column and back side bottom trim




Exterior  
20000D - Damage  
Jamb at back door chipped below strike plate




Exterior  
20070 - Tarnished Threshold  
Back door threshold tarnished




Exterior  
4000D - Damage  
Siding above and on each side of service disconnect stained




Exterior  
50000D - Damage  
Paint on all hinges of back door



Exterior  
50007 - Exterior Doors Missing Schlagggle  
Schlagel pads missing at back door



Exterior  
50007 - Exterior Doors Missing Schlagggle  
Schlagel pads missing at front door



Exterior  
500D - Damage  
Comer of patio broken behind hvac unit



Exterior  
500D - Damage  
Looking at home right edge of patio chipped near back wall



Exterior  
520 - Stain  
Stain on patio in middle of slab



Family Room  
1560 - Out of plumb/square  
Shoe mould on wall that is common with refrigerator space not square with floor



Garage  
520 - Stain  
Concrete splatter and paint on right side of slab at entrance



Garage  
520 - Stain  
Orange stains on slab in middle of rear section



Kitchen/Dinette  
1560 - Out of plumb/square  
Shoe mould on end of island near back door not square with floor



Kitchen/Dinette  
810 - Crooked Outlet/Switch  
On family room end of island, gap between receptacle plate and island panel



Stairs/Hall  
1520 - Miscut  
Ripped trim on side of attic stairs panel is uneven in width



Utility Room  
50000D - Damage  
Top of door dented

## Check List Item and Other Photos



