



New Review - Home Quality Review

Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Jaspers Landing SF (NC)(RAL)
Lot	00.0040
Street Address	53 Juniper Branch Trail
Field Manager	Thomas Crews
	Eric Morphy
Reviewer	Bill Beard
Date	5/8/2026
Type	New Review
Product Type	Detached

Score	94.60%
Second Look, Paint & Drywall?	No
Possible Points	125.00
Adj. Possible Points	125.00
Tic Marks	8
# of Items	23
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	1		0.25
Minor Paint	3		0.25
Minor Clean	4		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Plumbing	700D - Damage	Top edge of tub scratched near middle	0.25		
Bath - Owner's	Interior_Trim	1560 - Out of plumb/square	Shoe mould at left side sink bowed	0.25		
Bath - Powder	Plumbing	721 - Pedastal Sink Water Lines Visible	Water line visible on right side of pedestal sink	0.25		
Bedroom 1	Windows	13000D - Damage	Left rear bedroom bottom weather strip at rear window damaged on left side	0.25		
Bedroom 2	Doors	50005 - Missing Pieces	Left middle bedroom, door stop missing at entry door	0.25		
Exterior	Brick_Stone_Stucco	5000 - Miscellaneous	Paint on brick and front porch slab in front and on left side	0.25		
Exterior	Brick_Stone_Stucco	5000 - Miscellaneous	Excess mortar on brick left of front porch outlet	0.25		
Exterior	Cleaning	TIC	White mark on brick at left window of front porch	0		
Exterior	Concrete_Flatwork	520 - Stain	Patio stained in front of back door	0.25		
Exterior	Exterior_Trim	20050 - Ext. Trim Miscut	Kick board under back door miscut	0.25		
Exterior	Gutters_and_Downspout	3000 - Miscellaneous	Discharge outlet for right rear downspout above grade	0.25		
Exterior	Siding	4000D - Damage	J channel above left side of garage door scuffed	0.25		
Exterior	Siding	4030 - Soffit/Fascia Issues	Gap between left side front porch soffit and metal trim	0.25		
Family Room	Electric	810 - Crooked Outlet/Switch	Gap between wall and switch plate at back door	0.25		
Family Room	Low_Voltage	900 - Miscellaneous	Pulsing sound coming from fireplace	0.25		
Foyer	Cleaning	TIC	Paint on bottom weather strip at front door	0		
Garage	Framing	1000 - Miscellaneous	Anchor bolts exposed on front wall	0.25		
Kitchen/Dinette	Cabinets	1630 - Drawer/Door Issue	Drawer under oven not self closing tight to frame on left side	0.25		
Kitchen/Dinette	Cabinets	1620 - Missing Bumps	Bump missing at drawer right of dishwasher	0.25		
Kitchen/Dinette	Closet_Shelving	17005- Missing Pieces	In pantry closet, caps missing on right side of 2nd shelf from top	0.25		
Kitchen/Dinette	Interior_Trim	1560 - Out of plumb/square	Shoe mould left of pantry closet bowed	0.25		
Laundry Room	Electric	850 - Improper Switch/Outlet Location	Outlet for dryer not behind appliance	0.25		
Stairs/Hall	Cleaning	TIC	Paint on bottom weather strip at garage door	0		
Stairs/Hall	Doors	50040 - Door Rubs	Garage door rubs jamb at strike plate	0.25		
Stairs/Hall	Doors	50005 - Missing Pieces	Hinge bump missing at garage door	0.25		
Stairs/Hall	Interior_Trim	1560 - Out of plumb/square	Shoe mould on left side wall and shoe mould at bottom step not square with floor	0.25		

Scored Photos



Bath - Hall
700D - Damage
Top edge of tub scratched near middle




Bath - Owner's
1560 - Out of plumb/square
Shoe mould at left side sink bowed



Bath - Powder
721 - Pedestal Sink Water Lines Visible
Water line visible on right side of pedestal sink



Bedroom 1
13000D - Damage
Left rear bedroom bottom weather strip at rear window damaged on left side



Bedroom 2
50005 - Missing Pieces
Left middle bedroom, door stop missing at entry door



Exterior
20050 - Ext. Trim Miscut
Kick board under back door miscut



Exterior
3000 - Miscellaneous
Discharge outlet for right rear downspout above grade



Exterior
4000D - Damage
J channel above left side of garage door scuffed



Exterior
4030 - Soffit/Fascia Issues
Gap between left side front porch soffit and metal trim



Exterior
5000 - Miscellaneous
Excess mortar on brick left of front porch outlet




Exterior
5000 - Miscellaneous
Paint on brick and front porch slab in front and on left side



Exterior
520 - Stain
Patio stained in front of back door



Exterior
TIC
White mark on brick at left window of front porch



Family Room
810 - Crooked Outlet/Switch
Gap between wall and switch plate at back door




Family Room
900 - Miscellaneous
Pulsing sound coming from fireplace




Foyer
TIC
Paint on bottom weather strip at front door



Garage
1000 - Miscellaneous
Anchor bolts exposed on front wall



Kitchen/Dinette
1560 - Out of plumb/square
Shoe mould left of pantry closet bowed



Kitchen/Dinette
1620 - Missing Bumps
Bump missing at drawer right of dishwasher




Kitchen/Dinette
1630 - Drawer/Door Issue
Drawer under oven not self closing tight to frame on left side



Kitchen/Dinette
17005- Missing Pieces
In pantry closet, caps missing on right side of 2nd shelf from top




Laundry Room
850 - Improper Switch/Outlet Location
Outlet for dryer not behind appliance



Stairs/Hall
1560 - Out of plumb/square
Shoe mould on left side wall and shoe mould at bottom step not square with floor



Stairs/Hall
50005 - Missing Pieces
Hinge bump missing at garage door



Stairs/Hall
50040 - Door Rubs
Garage door rubs jamb at strike plate



Stairs/Hall
TIC
Paint on bottom weather strip at garage door

Check List Item and Other Photos



