



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	North First Street TH (NC)(RAL)
Lot	00.0018
Street Address	1286 Hammond Drive
Field Manager	Nickolas Cooke
	Matthew Wing
Reviewer	Darryl Hall
Date	5/20/2026
Type	New Review
Product Type	Townhouse

Score	96.00%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	17
# of Items	8
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	5		0.5
Minor Paint	8		1
Minor Clean	4		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Exterior	Exterior_Trim	20040 - Ext. Trim Not Pieced Together Properly	Drip edge, left side, front pitch, has inconsistent gaps.	0.25		
Exterior	Exterior_Trim	20040 - Ext. Trim Not Pieced Together Properly	Drip edge, rear pitch, left side, had inconsistent gaps.	0.25		
Exterior	Exterior_Trim	20040 - Ext. Trim Not Pieced Together Properly	Soffit on left rear pitch, is not pieced together well.	0.25		
Exterior	Exterior_Trim	20040 - Ext. Trim Not Pieced Together Properly	Drip edge, rear of townhouse, left pitch, had inconsistent gaps.	0.25		
Exterior	Paint	1700D - Damage	Rear threshold support had screw heads visible.	0.25		
Garage	Paint	1710 - Nail Holes Not Filled & Colored	Garage entry door, threshold support, has visible screws.	0.25		
Kitchen/Dinette	Appliances	1801 - Miscellaneous	Garbage disposal making a loud noise.	0.25		
Stairs/Hall	Stairs_and_Rails	21005 - Missing Pieces	Top handrail holder, is missing a screw.	0.25		

Photos

Scored Photos



Exterior
1700D - Damage
Rear threshold support had screw heads visible.



Exterior
20040 - Ext. Trim Not Pieced Together Properly
Drip edge, left side, front pitch, has inconsistent gaps.



Exterior
20040 - Ext. Trim Not Pieced Together Properly
Drip edge, rear of townhouse, left pitch, had inconsistent gaps.



Exterior
20040 - Ext. Trim Not Pieced Together Properly
Drip edge, rear pitch, left side, had inconsistent gaps.



Exterior
20040 - Ext. Trim Not Pieced Together Properly
Soffit on left rear pitch, is not pieced together well.



Garage
1710 - Nail Holes Not Filled & Colored
Garage entry door, threshold support, has visible screws.



Kitchen/Dinette
1801 - Miscellaneous
Garbage disposal making a loud noise.



Stairs/Hall
21005 - Missing Pieces
Top handrail holder, is missing a screw.

Check List Item and Other Photos





