



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek SF 30's (NC)(RAL)
Lot	00.0510
Street Address	1613 Briar Brook Lane
Field Manager	Daniel Morris
	Eric Morphy
Reviewer	Jason Weaver
Date	5/12/2026
Type	New Review
Product Type	Detached

Score	94.35%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	20
# of Items	17
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

8 to 12

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	2		0.25
Minor Paint	9		1
Minor Clean	9		1

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Drywall	1400 - Miscellaneous	Drywall bows out in left corner over the surround	0.25		
Bath - Hall	Framing	1030 - Out of Square/Level	Small wall right of the shower spout is not square	0.25		
Bath - Owner's	Cabinets	1630 - Drawer/Door Issue	Top hinge of right cabinet door under the right sink is loose	0.25		
Bath - Owner's	Ceramic	1220 - Tile Installation Issue	Small tile in top left back corner is leaning in towards wall over the bench	0.25		
Bath - Powder	Doors	5000D - Damage	Doorstop is not fully secured	0.25		
Bedroom 1	Drywall	1400 - Miscellaneous	Wave in drywall in top corner of left wall and wall with switch in the back right bedroom	0.25		
Bedroom 1	Interior_Trim	1500 - Miscellaneous	Inconsistent gap between baseboard and carpet underneath light switch in back right bedroom	0.25		
Bedroom 2	Interior_Trim	1560 - Out of plumb/square	Bowed baseboard on left wall under outlet closest to closet wall in front right bedroom	0.25		
Bedroom 2	Interior_Trim	1560 - Out of plumb/square	Bowed baseboard under window in front right bedroom	0.25		
Exterior	Roofing	2000D - Damage	Tom shingle on edge of roof at Apex on right side	0.25		
Exterior	Siding	4000D - Damage	Metal edge under shingles on right side of garage near front porch is bent	0.25		
Exterior	Siding	4000D - Damage	Metal edge under shingles on left side of home towards the back is bent	0.25		
Family Room	Windows	13010 - Difficult to Open	Far left window in family room difficult to open/close	0.25		
Family Room	Windows	13020 - Latch issues	Far left window cannot get lower sash down far enough to lock	0.25		
Kitchen/Dinette	Appliances	1830 - Installed Incorrectly	Dishwasher is crooked to the countertop	0.25		
Kitchen/Dinette	Interior_Trim	1560 - Out of plumb/square	Inconsistent gap on front of island between shoe mold and beadboard near the right side	0.25		
Stairs/Hall	Electric	855 - Other Installation Issue	Light switch at bottom of stairs, does not turn any lights on or off	0.25		

Scored Photos



Bath - Hall
1030 - Out of Square/Level
Small wall right of the shower spout is not square



Bath - Hall
1400 - Miscellaneous
Drywall bows out in left corner over the surround



Bath - Owner's
1220 - Tile Installation Issue
Small tile in top left back corner is leaning in towards wall over the bench



Bath - Owner's
1630 - Drawer/Door Issue
Top hinge of right cabinet door under the right sink is loose



Bath - Powder
50000D - Damage
Doorstop is not fully secured



Bedroom 1
1400 - Miscellaneous
Wave in drywall in top corner of left wall and wall with switch In the back right bedroom



Bedroom 1
1500 - Miscellaneous
Inconsistent gap between baseboard and carpet underneath light switch in back right bedroom



Bedroom 2
1560 - Out of plumb/square
Bowed baseboard on left wall under outlet closest to closet wall in front right bedroom



Bedroom 2
1560 - Out of plumb/square
Bowed baseboard under window in front right bedroom



Exterior
2000D - Damage
Torn shingle on edge of roof at Apex on right side



Exterior
4000D - Damage
Metal edge under shingles on left side of home towards the back is bent




Exterior
4000D - Damage
Metal edge under shingles on right side of garage near front porch is bent



Family Room
13010 - Difficult to Open
Far left window in family room difficult to open/close




Family Room
13020 - Latch issues
Far left window cannot get lower sash down far enough to lock



Kitchen/Dinette
1560 - Out of plumb/square
Inconsistent gap on front of island between shoe mold and beadboard near the right side



Kitchen/Dinette
1830 - Installed Incorrectly
Dishwasher is crooked to the countertop



Stairs/Hall
855 - Other Installation Issue
Light switch at bottom of stairs, does not turn any lights on or off

Check List Item and Other Photos





