



New Review - Home Quality Review

Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek SF 30's (NC)(RAL)
Lot	00.0513
Street Address	1601 Briar Brook Lane
Field Manager	Daniel Morris
	Eric Morphy
Reviewer	Jon Bennett
Date	5/29/2026
Type	New Review
Product Type	Detached

Score	96.30%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	8
# of Items	12
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules


Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	0		0
Minor Paint	7		1
Minor Clean	1		0.25

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Drywall	1400D -Damage	Right rear vertical corner above tub surround is wavy/curved	0.25		
Bedroom - Owner's	Electric	810 - Crooked Outlet/Switch	Back wall tv receptacle and data covers are both crooked	0.25		
Bonus	Drywall	1400D -Damage	2nd floor bonus room, corner of wall left of laundry room door has a flattened area on the corner edge	0.25		
Dining Room	Electric	811 - Light Crooked	Pendant light is hanging crooked	0.25		
Exterior	Concrete_Flatwork	520 - Stain	Dark stains/spots on left side driveway pad	0.25		
Exterior	Roofing	2000D - Damage	2nd level roof above front porch on left side, the shingle overhang and drip edge is damaged/compressed	0.25		
Family Room	Framing	1050 - Bowed Wall	Back wall in family room is bowed, far right of pedestrian door to garage	0.25		
Garage	Concrete_Flatwork	520 - Stain	White colored stains on concrete slab floor	0.25		
Kitchen/Dinette	Electric	810 - Crooked Outlet/Switch	Receptacle cover on far left of backsplash on rear wall, is out of alignment compared to the others	0.25		
Kitchen/Dinette	Plumbing	700D - Damage	Scrapes and scratches throughout bottom of sink	0.25		
Laundry Room	Plumbing	707 - Laundry Supply Box or Shutoff Access Issues	Supply box outer ring is not secure, easily comes off	0.25		
Stairs/Hall	Flooring	1350 - Carpet Installation	Mud/orange spot on left side of top rise of steps	0.25		

Scored Photos




Bath - Hall
1400D - Damage
Right rear vertical corner above tub surround is wavy/curved



Bedroom - Owner's
810 - Crooked Outlet/Switch
Back wall tv receptacle and data covers are both crooked



Bonus
1400D - Damage
2nd floor bonus room, corner of wall left of laundry room door has a flattened area on the corner edge



Dining Room
811 - Light Crooked
Pendant light is hanging crooked



Exterior
2000D - Damage
2nd level roof above front porch on left side, the shingle overhang and drip edge is damaged/compressed



Exterior
520 - Stain
Dark stains/spots on left side driveway pad



Family Room
1050 - Bowed Wall
Back wall in family room is bowed, far right of pedestrian door to garage



Garage
520 - Stain
White colored stains on concrete slab floor



Kitchen/Dinette
700D - Damage
Scrapes and scratches throughout bottom of sink



Kitchen/Dinette
810 - Crooked Outlet/Switch
Receptacle cover on far left of backsplash on rear wall, is out of alignment compared to the others



Laundry Room
707 - Laundry Supply Box or Shutoff Access Issues
Supply box outer ring is not secure, easily comes off



Stairs/Hall
1350 - Carpet Installation
Mud/orange spot on left side of top rise of steps

Check List Item and Other Photos



