



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek SF 30's (NC)(RAL)
Lot	00.0514
Street Address	1589 Briar Brook Lane
Field Manager	Zachery Semple
	Eric Morphy
Reviewer	Bill Beard
Date	6/10/2026
Type	New Review
Product Type	Detached

Score	93.91%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	12
# of Items	23
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

8 to 10

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	1		0.25
Minor Paint	6		0.5
Minor Clean	5		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Interior_Trim	1560 - Out of plumb/square	Shoe mould on right side of linen closet not square with floor	0.25		
Bath - Hall	Paint	1730 - Item Not Painted	Trim on left side of vanity not painted	0.25		
Bath - Owner's	Cleaning	TIC	Paint overspray on right side of vanity toe kick	0		
Exterior	Brick_Stone_Stucco	5000 - Miscellaneous	Excess caulk at door chime button	0.25		
Exterior	Cleaning	TIC	SGD track dirty	0		
Exterior	Concrete_Flatwork	520 - Stain	Patio slab stained	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Gouge in right side of front porch slab	0.25		
Exterior	Exterior_Trim	20000D - Damage	Trim at left side hose bib stained	0.25		
Exterior	Exterior_Trim	20000D - Damage	Kick board at front door miscut along bottom and right edge	0.25		
Exterior	HVAC	600 - Miscellaneous	Mud on hvac platform	0.25		
Exterior	HVAC	600D - Damage	Trim at right side vent stained	0.25		
Exterior	Landscaping	300D - Damage	Sod in left side of front yard at curb disturbed	0.25		
Exterior	Siding	4000 - Miscellaneous	House wrap visible on both sides of SGD	0.25		
Exterior	Siding	4020 - J Channel/Trim Not Square	Bottom j channel at right side vent crooked	0.25		
Exterior	Siding	4020 - J Channel/Trim Not Square	Inconsistent reveal between siding and j channel at front water tables	0.25		
Garage	Framing	1000 - Miscellaneous	Black marks on framing on each side of garage door	0.25		
Kitchen/Dinette	Appliances	1800D - Damage	Top left of dishwasher door stained	0.25		
Kitchen/Dinette	Cabinets	1605 - Missing Pieces	Crack between bead board on front of island	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Front comer trim on left side of island chipped	0.25		
Kitchen/Dinette	Cabinets	1610 - Manufacturer	Filler strip left of microwave not matching cabinets	0.25		
Kitchen/Dinette	Cabinets	1630 - Drawer/Door Issue	Middle drawer left of range tight	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Wall cabinet right of refrigerator, bottom frame on right side damaged	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Bottom frame at 1st and 2nd base cabinets intersection right of refrigerator chipped	0.25		
Kitchen/Dinette	Cleaning	1925 - Shipping Materials/Labels	Labels on left side of refrigerator	0.25		
Kitchen/Dinette	Interior_Trim	1560 - Out of plumb/square	Shoe mould on each side of pantry door not square with floor	0.25		

Scored Photos



Bath - Hall
1560 - Out of plumb/square
Shoe mould on right side of linen closet not square with floor



Bath - Hall
1730 - Item Not Painted
Trim on left side of vanity not painted



Bath - Owner's
TIC
Paint overspray on right side of vanity toe kick



Exterior
20000D - Damage
Kick board at front door miscut along bottom and right edge



Exterior
20000D - Damage
Trim at left side hose bib stained



Exterior
300D - Damage
Sod in left side of front yard at curb disturbed



Exterior
4000 - Miscellaneous
House wrap visible on both sides of SGD



Exterior
4020 - J Channel/Trim Not Square
Bottom j channel at right side vent crooked



Exterior
4020 - J Channel/Trim Not Square
Inconsistent reveal between siding and j channel at front water tables



Exterior
5000 - Miscellaneous
Excess caulk at door chime button



Exterior
500D - Damage
Gouge in right side of front porch slab



Exterior
520 - Stain
Patio slab stained




Exterior
600 - Miscellaneous
Mud on hvac platform



Exterior
600D - Damage
Trim at right side vent stained



Exterior
TIC
SGD track dirty



Garage
1000 - Miscellaneous
Black marks on framing on each side of garage door



Kitchen/Dinette
1560 - Out of plumb/square
Shoe mould on each side of pantry door not square with floor



Kitchen/Dinette
1600D - Damage
Bottom frame at 1st and 2nd base cabinets intersection right of refrigerator chipped



Kitchen/Dinette
1600D - Damage
Front corner trim on left side of island chipped



Kitchen/Dinette
1600D - Damage
Wall cabinet right of refrigerator, bottom frame on right side damaged




Kitchen/Dinette
1605 - Missing Pieces
Crack between bead board on front of island



Kitchen/Dinette
1610 - Manufacturer
Filler strip left of microwave not matching cabinets



Kitchen/Dinette
1630 - Drawer/Door Issue
Middle drawer left of range tight



Kitchen/Dinette
1800D - Damage
Top left of dishwasher door stained



Kitchen/Dinette
1925 - Shipping Materials/Labels
Labels on left side of refrigerator

Check List Item and Other Photos



