Kestrel Body Repairs

Unit 4, Mill Lane Trading Estate, Leeds LS12 6AB
Approved repairer

Repair estimate
Estimate KBR-24833
14 October 2026

Customer	Tom Brennan
Vehicle	Saloon, white
Registration	LB21 RWT
Damage	Struck from behind while stationary at a junction.

Item	Amount
Rear bumper cover, replace and paint	£398.00
Boot lid, repair and paint	£310.00
Right tail lamp	£176.00
Rear bumper reinforcement	£122.00
Labour, 6 hours at £58	£348.00
Paint and materials	£95.00
Subtotal	£1,449.00
VAT at 20%	£289.80
Total	**£1,738.80**

Valid for 30 days. Parts are new manufacturer parts unless stated.