



February 27, 2004

## C8051F350/1/2/3 Errata (Rev. B)

The following errata apply to revision B of the C8051F350, C8051F351, C8051F352, and C8051F353 devices:

 When using the internal voltage reference (V<sub>REF</sub>), there may be some tonal noise when the input voltage to the ADC is near 0 V. An external voltage reference source is recommended when using the ADC on revision B silicon.