Power in AC circuits	9-20	Polyimides	/-/
Resistance	9-12	Polyurethane	8-5
True power	9-20	Poor adhesion	8-13
Optical considerations		Pop rivets	4-56
Orange peel	8-14	Portable power drills	
Other aircraft inspection and maintenance		Power factor	9-20
programs		Powerplant	1-42, 2-34
Outside the member		Powerplant stations	1-39
Oven		Power systems	9-41
Overhead position welding		Power tools	4-37
Oxidizing flame		Preflight	2-60
Oxy-acetylene cutting		Pre-impregnated products (prepregs)	7-8
Oxy-acetylene welding of ferrous metals		Preparation of wood for gluing	6-11
Oxy-acetylene welding of nonferrous metals		Preparing glues for use	6-11
Oxygen	5-7	Prepreg	7-27
_		Press brake	4-23
P		Pressing or clamping time	6-11
Paint booth	8-6	Pressure	2-2
Paint finishes	8-19	Pressure on the joint	6-12
Paint system compatibility	8-19	Pressure regulators	5-7
Paint touchup		Pressurization	1-10
Paper decals	8-18	Primary flight controls	2-11
Parasite drag		Primary flight control surfaces	1-24
Paste adhesives	7-9	Primer	3-7
Patches	4-97	Primer and paint	8-10
Patch installation on the aircraft	7-42	Primers	8-3
Peel ply	7-21	Profile drag	2-8
Pens	4-4	Progressive inspection	2-60
Perforated release film	7-21	Protective equipment for personnel	
Periodic maintenance inspections	2-60	Puddle	5-15
Phenolic resin	7-7	Pull-type blind bolt	4-54
Piccolo former	4-26	Pulse echo ultrasonic inspection	7-18
Pin fastening systems (high-shear fasteners)	4-50	Punches	4-5
Pinholes	8-14		
Pinked edge	3-3	R	
Pitting	4-91	Radiography	7-18
Plasma arc cutting	5-7	Radius dimpling	
Plasma arc welding	5-6	Radome repairs	
Plastic media blasting (PMB)	8-21	Reamers	
Plug patch	6-21	Rebalancing methods	2-38
Ply	3-3	Rebalancing procedures	
Ply orientation warp clock	7-29	Reciprocating engine	
Plywood skin repairs	6-20	Reciprocating saw	
Pneumatic circular cutting saw	4-8	Red Baron's Fokker DR-1	
Pneumatic drill motors	4-15	Red iron oxide	
Pneumatic rivet gun	4-37	Regulators	
Polishing	7-57	Reinforcing tape	
Polybenzimidazoles (PBI)		Relays	
Polyester fabric repairs		Release agents	
Polyester resins		Relief hole location	
Polyether ether ketone (PEEK)		Removal of decals	8-19