

From: Owen R. officeexecutorowenrobertlewis@gmail.com
Subject: Enquiry — Lal Lal Wind Farm Blade Failure Incident
Date: 24 May 2026 at 11:41 am
To: Info Lal Lal info@lallalwindfarms.com.au

OR

Dear Sir/Madam,

The Trustee refers to the blade failure incident associated with turbine YSTW23 at the Yendon section of the Lal Lal Wind Farm occurring on 15 May 2026.

The Trustee further refers to correspondence issued by Lal Lal Wind Farm dated 19 May 2026 concerning the incident.

The Trustee notes that material has recently been provided to the Trustee by the **Beneficiary** for administrative and record purposes relating to the incident, including photograph material, video footage material, and associated correspondence.

The Trustee further notes that the **Beneficiary** confirmed that the photograph and video footage material was supplied to him by another individual prior to being provided to the Trustee.

The Trustee notes that the material appears to depict debris associated with the incident dispersed across surrounding paddocks as at 23 May 2026, and no remediation, recovery, or containment activity is apparent within the material provided to the Trustee.

The Trustee also notes that documentary material previously disclosed through Environment Protection Authority Victoria Freedom of Information processes has referred to an earlier turbine blade incident within the Yendon section of the Lal Lal Wind Farm and associated disposal or recovery activities relating to blade material.

The Trustee further notes that the earlier enquiry issued by the **Beneficiary** on 15 May 2026 raised questions concerning:

- debris containment and recovery works;
- assessment of nearby drainage lines, waterways, or surrounding land;
- notification of relevant environmental or water authorities; and
- any environmental or public health assessment process associated with the incident.

The Trustee notes that the response issued by Lal Lal Wind Farm on 19 May 2026 provided general information concerning the incident and operational response, however the Trustee is presently unclear whether the specific matters raised in the **Beneficiary's** earlier enquiry were substantively addressed or remain under active consideration.

In light of the material now received by the Trustee, the Trustee respectfully enquires whether:

- debris recovery, containment, or remediation activities associated with turbine YSTW23 remain ongoing;
- any assessment has been undertaken regarding the apparent extent of debris dispersion associated with the incident;
- any assessment of surrounding land, drainage lines, or waterways has been undertaken in connection with the incident;
- any relevant environmental, water, or public authority notification process has occurred; and
- any updated community information concerning remediation, recovery, or site management is anticipated.

The Trustee is presently seeking clarification directly from Lal Lal Wind Farm concerning the matters referred to above prior to considering whether any further administrative or record communication is required in relation to the material presently held by the Trustee.

This enquiry is made for information and record purposes only.

The Trustee makes no allegation and asserts no finding concerning the incident, the condition of the site, or any associated operational, environmental, or regulatory matter.

Kind regards,

LEWIS TROJAN HORSE PTY LTD

(ACN 693 680 509)

as Trustee of the **Owen Robert Inter Vivos Trust**