Label	<b>Assembly</b>	ADDR	Data	Comment
START:	LDIA	00	04	Start at one.
	01	01	01	
LOOP1:	OUTA	02	3 <b>A</b>	Display results.
	TAB	03	0C	Double Number.
	ADDB	04	13	
	JNC	05	33	Do it again IF No Carry (Overflow).
	LOOP1:	06	02	
	CLC	07	20	No reason, really.
	JMP	08	30	Start over at one.
	START:	09	00	