Change List

2023/06/12 v1.4.9

		Description
	Modifications	1. Modify the timeout of copy image cmd
		1. EAPs issue
	Fixes	2. Reset cmd issue
		3. Image version format

2023/04/14 v1.4.8

		Description
	Additions	1. Support different EAPs
		1. Get image versions issue
	Fixes	2. Not support buffer check issue
		3. User data ota issue

2023/01/13 v1.4.7

	Description	Interfaces Involved
	1. Refactor	Delete -DFUUpgrade:withDevice:showFeatureInfoAvailable:andConsistency:withStartHandler:inRTKDFURoutine.h
Modifications	Indifications SDK	Rename -updateConnectionParameterWithMinInterval:maxInterval:latency:suspervisionTimeout:completionHandler:to -

2022/12/06 v1.4.6

Description

1. Support test mode

Modifications	SDK	Rename -updateConnectionParameterWithMinInterval:maxInterval:latency:suspervisionTimeout:completionHandler:to - updateConnectionParameterWithMinInterval:maxInterval:latency:supervisionTimeout:completionHandler:in RTKDFUConnectionUponGATT.h

Add setModeToStressTestWithCompletionHandler in RTKDFURoutine.h

 $\begin{tabular}{ll} Add image Feature in {\tt RTKOTAUpgradeBin.h} \\ \end{tabular}$

2022/11/11 v1.4.5

Additions

	Description	Interfaces Involved
		Add activeVPID in RTKDFUUpgrade.h
	1. Support VP ID Update	Add canUpdateVPID in RTKOTADeviceInfo.h
		Add VPID in RTKOTAUpgradeBin.h
Additions		Add - (void)checkFeatureInfoConsistencyOfImages:withCompletionHandler:inRTKDFURoutine.h
	2. Support checking image feature	Add - (void)DFUUpgrade:withDevice:showFeatureInfoAvailable:andConsistency:withStartHandler:inRTKDFUUpgrade.h
		Add checkFeatureInfo in RTKDFUUpgrade.h

2022/10/10 v1.4.4

		Description
Fixes		1. Crash issue caused by disconnection during upgrade
	Fixes	2. OTA failed due to incorrect connection status after switching to OTA mode
		3. Crash issue due to waiting for characteristics write response out of order

Interfaces Involved

2022/09/05 v1.4.3

	Description
Additions	1. Support new IC 14
Modifications	1. Update OTASDKDemo

2022/07/27 v1.4.2

	Description	Interfaces Involved
Additions	Support strict image check mechanism	Add usingStrictImageCheckMechanism in RTKDFUUpgrade.h

2022/06/22 v1.4.1

	Description	Interfaces Involved
Additions	1. Support for checking pub key (0x12)	Add - (void) checkImagesKeyOfCount: andKeyInfo: withCompletionHandler: in RTKDFURoutineGATT.h
	1. Modify the value of invalid image version	
F.	2. Change the wait time for reconnection	
Fixes	3. Fix the issue caused by header files error	
	4. Fix the battery check condition	

2022/05/23 v1.4.0

	Description	Interfaces Involved
Additions	1. Support opcode 0x12 (report image number)	Add - (void)reportImageID:currentImageNumber:totalImageNumber:withCompletionHandler: in RTKDFURoutineGATT.h
	2.Get inactive Bins informations during the prepareForUpgrade process	Add inactiveBins in RTKOTADeviceInfo.h
Fixes	1. Fix demo issue: after the first upgrade, the OTAProfile becomes nil and then the device cannot be connected again.	
	2. Fix some process issues in the new SDK	

2022/04/28 v1.3.10

		Description
	A 1 1111	1. Refactor the SDK
Additions	2.Support IAP	

2022/03/10 v1.3.0

	Description
Additions	1. Support protocol type = 0x0012
Modifications	1. Modify image name

2022/02/28 v1.2.1

	Description
Fixes	1. Fix CMD0x04 format

2022/01/20 v1.2.0

	Description
Modifications	1. Modify DSP Config/DSP APP/DSP SYS/LowerStack/VP file version format

2021/12/22 v1.1.29

	Description	Interfaces Involved
	1. Support VP Upgrade(For AT)	Add canUpdateVP and isVPMode in RTKOTAPeripheral
Additions	2. Support protocol = 0x0013	Change the type of protocolType from RTKOTAProtocolType to uint16_t in RTKOTAPeripheral
	3. Support 8763E watch OTA	Add -[RTKMultiDFUPeripheral reorderFiles]
Modifications	1. Modify imageType	
Fixes	1. Fix crash issue caused by file parsing error (length = 0 in MPHeader)	

2021/12/13 v1.1.28

	Description
Modifications	1.Modify imageId
Fixes	1. Fix an issue where Ext2 is not packaged in the upgrade file

2021/11/19 v1.1.27

	Description
Modifications	1.Modify image header offset

2021/11/05 v1.1.26

	Description
NA UC	1.Modify SHA256 offset
Modifications	2. Support 8763E OTA
Fixes	1.Fix crash issues caused by repeated definition of errors

v1.1.24

	•
	Description
Additions	1.Print framework version

v1.1.22

	Description
Additions	1.Add support for app to delay active image