After sensor is occupied by glass and all of popup's workstation is full, conveyor can't send glass to sensor until popup give sensor msgIAmEmpty() and sensor clean its space

1.msgCanISendGlass()



