

- 1. Problem: Inner Tie Rod Noise
- 2. Results
 - 1) Steering Gear Assembly
 - Appearance/Dimension/Leakage/Lash Test & Torque Test(I.T.R & O.T.R) : No issue

Model	Check Appearance	Check Result
T250	Outer Tie Rod	ОК
J200	Inner Tie Rod	ОК



3. Possible Root Cause

→ For inner tie rod and outer tie rod noise, ball stud of outer tie rod and up/down movement of knuckle occur while driving on uneven road surfaces, and due to friction. The same phenomenon occurred in other vehicle, it was confirmed as the same content.

