
Thermal Fuse Open


[Resistor ASM - GSVEM HVAC]

UzECC

Thermal Fuse Open in Resistor ASM(52429971)

- Issue
 - Blower motor does not work at speed # 4 in vehicle condition.
- Root Cause
 - Thermal fuse was opened to protect system.
 - It's from electric shock in vehicle condition.





UzECC Process

- **Test 100%** with function tester
- Check ampere and resistance with connecting resistor and blower motor for each speed

