

Facade refurbishment technical note

SYNTHETIC DEMO - fictional project records - NOT FOR CONSTRUCTION

BJM-B27-TN-008 Revision P01 22 April 2025

Purpose and decision

This fictional design-development note compares two facade refurbishment options for Block B. Retain the existing structural frame and develop a ventilated cladding option for the next coordination review. No product certification or regulatory compliance is established by this note.

Existing conditions

The sample inspection records local sealant failure, uneven panel joints and staining near balcony slab edges. These observations are invented and describe a limited visual inspection scenario. Intrusive testing and actual survey evidence would be needed for a real project.

Options for coordination

Option A uses insulated render. Option B uses a ventilated panel system. Both need resolved interfaces at balcony brackets, window returns and the ground-floor plinth. The architectural team should issue a typical detail before confirming quantities.

Actions and dependencies

RFI-014: confirm the accessible entrance threshold arrangement. RFI-018: coordinate the rainwater pipe within the facade zone. The mock envelope specialist will review a sample bay on 6 May 2025. Values below are scenario inputs, not construction specifications.

Item	Option A	Option B
Finish	Insulated render	Ventilated panel
Sample allowance EUR/m2	145	210
Decision status	Reserve	Develop further