

Lock-in amplifier

Measuring input

Oscillator voltage out

V_{meas}

V_0 rms

R_0

1

2

C_p

4

3

sample

