

Lock-in amplifier

Measuring input

Oscillator voltage out

V_{meas}

V_0 rms

R_0

R_D

C_p

I_+

V_+

V_-

I_-

