

SYNTHETIC DEMO - DDR - OFF-07

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-07; Event: mud_loss; Formation: TIPAM_A; MD: 2619.57-2624.57 m; TVD: 2410.00 m;
Severity: warning; Observation: Historical synthetic mud_loss reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-07

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-07; Event: stuck_pipe; Formation: TIPAM_A; MD: 2645.65-2650.65 m; TVD: 2434.00 m;
Severity: warning; Observation: Historical synthetic stuck_pipe reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-07

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-07; Event: kick_or_overpressure; Formation: TIPAM_A; MD: 2671.74-2676.74 m; TVD: 2458.00 m; Severity: warning; Observation: Historical synthetic kick_or_overpressure reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-07

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-07; Event: torque_drag; Formation: TIPAM_A; MD: 2697.83-2702.83 m; TVD: 2482.00 m;
Severity: warning; Observation: Historical synthetic torque_drag reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-07

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-07; Event: cementing_issue; Formation: TIPAM_A; MD: 2723.91-2728.91 m; TVD: 2506.00 m; Severity: warning; Observation: Historical synthetic cementing_issue reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-07

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-07; Event: fishing; Formation: TIPAM_A; MD: 2750.00-2755.00 m; TVD: 2530.00 m; Severity: warning; Observation: Historical synthetic fishing reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h