

SYNTHETIC DEMO - DDR - OFF-01

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-01; Event: stuck_pipe; Formation: TIPAM_B; MD: 2410.00-2415.00 m; TVD: 2410.00 m;
Severity: warning; Observation: Historical synthetic stuck_pipe reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-01

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-01; Event: kick_or_overpressure; Formation: TIPAM_B; MD: 2434.00-2439.00 m; TVD: 2434.00 m; Severity: warning; Observation: Historical synthetic kick_or_overpressure reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-01

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-01; Event: torque_drag; Formation: TIPAM_B; MD: 2458.00-2463.00 m; TVD: 2458.00 m;
Severity: warning; Observation: Historical synthetic torque_drag reported; Mitigation: Engineering review
and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-01

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-01; Event: cementing_issue; Formation: TIPAM_B; MD: 2482.00-2487.00 m; TVD: 2482.00 m; Severity: warning; Observation: Historical synthetic cementing_issue reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-01

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-01; Event: fishing; Formation: TIPAM_B; MD: 2506.00-2511.00 m; TVD: 2506.00 m; Severity: warning; Observation: Historical synthetic fishing reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h

SYNTHETIC DEMO - DDR - OFF-01

Date: 2025-02-01; dataset_origin: synthetic_demo

Well: OFF-01; Event: npt; Formation: TIPAM_B; MD: 2530.00-2535.00 m; TVD: 2530.00 m; Severity: warning; Observation: Historical synthetic npt reported; Mitigation: Engineering review and documented site procedure used; Outcome: Synthetic incident resolved; NPT: 2 h