



WARNING:

AFTER A RESET THE BOARD WILL NOT REBOOT UNTIL A SECOND RESET WILL OCCUR OR AFTER THE 60-SECONDS BOOT FAILURE TIME-OUT INTERVENTION,
ACCORDING TO THE FUNCTIONAL PROBLEM NAMED SPIFI.I EXPLAINED IN THE NXP
ERRATA SHEET REV. 2.2 - 8 AUGUST 2012.




THE ROM DRIVER DOES NOT RE-INITIALIZE THE EXTERNAL FLASH DEVICE.








DISPLAY


UMSH-8065MD-17T













LAYOUT :
SEE PAGE 37
OF DATA SHEET





EXPANSION CONNECTORS

