



August 1, 2022

Mr. Blue Parrish or Ms. Carissa Money
Colorado Department of Public Health and Environment
Air Pollution Control Division
Operating Permits Unit
APCD-SS-B1
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

Via Email

RE: Title V Semiannual Monitoring and Permit Deviation Report – 1/1/2022 to 6/30/2022
Title V Operating Permit 95OPBO082
CEMEX Lyons Cement Plant; Facility AIRS ID - CO 0130003

Dear Mr. Parrish and/or Ms. Money:

Enclosed is the Semiannual Monitoring and Permit Deviation Report for the reporting period January 1, 2022 through June 30, 2022 as required by Title V Operating Permit 95OPBO082 of the Lyons Cement Plant, Facility AIRS ID - CO 0130003.

Please contact me at (303) 823-2124 or through my email, scotta.harcus@cemex.com, should you have questions or concerns about this submittal.

Sincerely,

**Scott Adam
Harcus**

Digitally signed by Scott Adam Harcus
DN: cn=Scott Adam Harcus, o=CEMEX
Constructions Materials South LLC,
ou=Cement Operations,
email=scotta.harcus@cemex.com, c=US
Date: 2022.08.01 17:08:49 -06'00'

Scott A. Harcus
Environmental Manager
Lyons Cement Plant

Cc: Mr. Dave Huber, CDPHE, via email
Ms. Gabi Hoefler, BCPH, via email

Lyons Cement Plant – an ISO 14001 Certified Facility ISO 14001-00023163
P O Box 529, Lyons, CO 80540
Phone (303) 823-2100, Fax (303) 823-2199

T5 SAR

Semiannual Title V Monitoring and Permit Deviation Report

Operating Permit 95OPBO082

AIRS ID 013-0003

CEMEX Lyons Cement Plant

1/1/2022 to 6/30/2022

APPENDIX D

Notification Addresses

1. **Air Pollution Control Division**

Air Pollution Control Division
Operating Permits Unit
APCD-SS-B1
4300 Cherry Creek Drive S.
Denver, CO 80246-1530

ATTN: Blue Parrish or Carissa Money

2. **United States Environmental Protection Agency**

Compliance Notifications:

Office of Enforcement, Compliance and Environmental Justice
Mail Code 8ENF-T
U.S. Environmental Protection Agency, Region VIII
1595 Wynkoop Street
Denver, CO 80202-1129

Note: Deviation reports shall be submitted to the Division at the address given in Appendix D of this permit. No copies need be sent to the U.S. EPA.

SUBMITTAL DEADLINES

First Semi-Annual Monitoring Period:	March 1 – June 30
Subsequent Semi-Annual Monitoring Periods:	July 1 – December 31, January 1– June 30
Semi-Annual Monitoring Reports:	Due August 1, 2008 & February 1, 2009 & subsequent years
First Annual Compliance Period:	March 1 - December 31

Monitoring and Permit Deviation Report - Part I

Operating Permit Unit ID	Unit Description	Deviations Noted During Period? ¹		Deviation Code ²	Malfunction/ Emergency Condition Reported During Period?	
		YES	NO		YES	NO
P017	Dowe Flats Quarry Fugitive Emission Sources & Lyons Quarry	X		3	X	
P017	Dowe Flats Quarry – Point Source Emissions		X			
P018	General Fugitive Emissions Requirements	X		9		X
P000	Raw Material Storage and Handling at Plant Site	X		3	X	
P001	Primary Crusher (Plant Site)		X			
P002	Raw Materials Drying		X			
P003	Secondary Crushing, Screen, Silo, Belt Transfer		X			
P004	Raw Materials Storage Silos	X		9		X
P005	Raw Mill Grinding		X			
P006	Homogenizing and Blending		X			
P007 & P008	Kiln Burning and Clinker Cooling and Transfer to Storage for Finish Mill	X		1		X
P009	Clinker and Gypsum/Additive Silos and Weigh Feeders (Storage and Transfer to Finish Mill)		X			
P010	Sheltered (A-Frame) Clinker Storage and Reclaim		X			
P015	Outdoor Clinker Piles and Handling	X		3	X	
P011 & P012	Cement Finish Mill and Auxiliaries		X			
P013	Cement Silos/Packhouse/Loadout		X			
P014	Material Handling System – Load-In and Load-Out		X			
P007A	Handling and Processing of CKD and Raw Material Waste Dust	X		3	X	
P050	Cement Rail Car Unloading System		X			
	Gasoline Storage Tank		X			
	Cold Cleaner Solvent Vats		X			
LIS-1	Lime storage silo		X			
LIS-2	Lime weigh hopper		X			
A-Pit Pump	Diesel fuel-fired engine, rated at 90 hp.		X			
DF 6" Pump	Diesel fuel-fired engine, rated at 80 hp		X			
DF 8" Pump	Diesel fuel-fired engine, rated at 84 hp		X			
Kiln Engine	Natural gas-fired engine, rated at 230 hp (Emergency Engine)		X			
Flood Engine	Diesel fuel-fired engine, rated at 99 hp (Emergency Engine)		X			
	Insignificant Activities		X			
	General Conditions		X			

¹ See previous discussion regarding what is considered to be a deviation. Determination of whether or not a deviation has occurred shall be based on a reasonable inquiry using readily available information.

²Use the following entries as appropriate:

- | | |
|-------------------------|---|
| 1 = Standard: | When the requirement is an emission limit or standard |
| 2 = Process: | When the requirement is a production/process limit |
| 3 = Monitor: | When the requirement is monitoring |
| 4 = Test: | When the requirement is testing |
| 5 = Maintenance: | When required maintenance is not performed |
| 6 = Record: | When the requirement is recordkeeping |
| 7 = Report: | When the requirement is reporting |
| 8 = CAM: | A situation in which an excursion or exceedance as defined in 40 CFR Part 64 (the Compliance Assurance Monitoring (CAM) Rule) has occurred. |
| 9 = Other: | When the deviation is not covered by any of the above categories |

Monitoring and Permit Deviation Report - Part II

1/31/2022 – Fugitive Dust Event

Is the deviation being claimed as an: Emergency _____ Malfunction _____ N/A XX

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation _____

OPERATING PERMIT UNIT IDENTIFICATION: P018 General Fugitive Dust

Operating Permit Condition Number Citation: No clear violation or permit condition. Documentation of Fugitive Dust Events performed in compliance with permit requirements

Explanation of Period of Deviation

High wind speed event caused fugitive dusting from the region, including various areas across the plant property.

Duration (start/stop date & time):

Start: 1/31/2022, 14:54 MST

End: 1/31/2022, 14:59 MST

Action Taken to Correct the Problem:

Operator ran the Water Truck all day before, during and after the event.

Measures Taken to Prevent a Recurrence of the Problem:

To prevent a recurrence, CEMEX initiated major repair works on the Crusher/Dryer system. C-pit Compaction and Capping activities were enhanced. CEMEX submitted C-pit Material Handling Plan to DRMS as Technical Revision #17 of the Lyons Quarry Permit 77-208.

Date of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9-Others

Division Code QA: _____

Monitoring and Permit Deviation Report - Part II

2/27/2022 – Kiln Opacity Exceedance

Is the deviation being claimed as an: Emergency _____ Malfunction _____ N/A XX _____

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown XX _____ Malfunction _____
Normal Operation _____

OPERATING PERMIT UNIT IDENTIFICATION: P007– Kiln Burning, Precalciner Kiln (Stack # S016), Baghouse # 525-14

Operating Permit Condition Number Citation: Part II, Conditions 10.9.1 and 10.22.1.3

Explanation of Period of Deviation

Kiln opacity exceeded the 20% limit for 6 minutes from 6:54 to 6:59. Compressor Lines froze, and the Kiln was shut down for approximately 30 minutes. Due to the loss of air, draft was lost on the Kiln ID fan. Root cause: lack of winterization (insulation, anti-freeze modifications).

Duration (start/stop date & time):

Start: 2/27/2022, 6:54 MST

End: 2/27/2022, 6:59 MST

Action Taken to Correct the Problem: Restored operation to Kiln Baghouse Air Damper(s)

Measures Taken to Prevent a Recurrence of the Problem:

To prevent a recurrence, CEMEX has installed sufficient insulation to the compressed gas lines and controls.

Date of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 1- Standard

Division Code QA: _____

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation XX

OPERATING PERMIT UNIT IDENTIFICATION: P007– Kiln Burning, Precalciner Kiln (Stack # S016), Baghouse # 525-14

Explanation of Period of Deviation:

Duration (start/stop date & time):

Start: 4/21/2022, 05:37 MDT

Stop: 4/21/2022, 05:42 MDT

Action Taken to Correct the Problem: The compromised compartment was shut down immediately, lowering opacity to compliance level.

Measures Taken to Prevent a Recurrence of the Problem: Reminded operations and maintenance teams to perform inspections prior to restoring baghouse compartment operation.

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 1-Standard

Division Code QA: _____

Monitoring and Permit Deviation Report - Part II 4/21/2022 – Raw Material Silos Dusting

Is the deviation being claimed as an: Emergency _____ Malfunction _____ N/A XX

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation _____ XX

OPERATING PERMIT UNIT IDENTIFICATION:

AIRS Pt. 004 – Raw Material Storage Silos (Stack # S006, Baghouse # 225-15)

Operating Permit Condition Number Citation: Part II, Condition 22.15

Explanation of Period of Deviation:

On 4/21/2022, at about 6:05 to 6:10 MDT, a plume from the Raw Material silos was observed. Investigation revealed that 229-7 Belt Discharge chute plugged, causing material to back up, and eventually create a dust event in the area.

Duration (start/stop date & time):

Start: 4/21/2021, 6:05 MDT

Stop: 4/21/2021, 6:10 MDT

Action Taken to Correct the Problem: The Crusher/Dryer system was shut down immediately and the plugged chute was cleared prior to restart.

Measures Taken to Prevent a Recurrence of the Problem:

To eliminate recurrence, employees reminded to keep Plugged Chute Sensors active and to follow pre-startup checklists to ensure sensors are properly installed.

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9-Others

Division Code QA: _____

Monitoring and Permit Deviation Report - Part II 6/9/2022 – Fugitive Dust Event

Deviation being claimed as an: Emergency _____ Malfunction _____ N/A XX

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation XX

OPERATING PERMIT UNIT IDENTIFICATION: AIRS Pt. 004 (P004-Raw Materials Storage Silos)

Operating Permit Condition Number Citation: Part II, Condition 22.15

Explanation of Period of Deviation:

On June 9, 2022, CEMEX Lyons experienced a 5-minute dust event from 16:33-16:38 during a sustained high wind event. It was concluded that the belt conveyor (229-7) transporting raw rock materials to the silos had a 3 ft tear creating material accumulation on top of the Raw Material Silos. During this event, the Lyons Plant water truck was on the watering routes around the A-frame and the sweeper truck was working around the Dryer area.

Duration (start/stop date & time):

Start: 6/9/2022. 16:33 MDT

Stop: 6/9/2022. 16:38 MDT

Action Taken to Correct the Problem:

During belt preventive maintenance, the maintenance crew identified the damage to the (229-7) belt and the belt was repaired immediately.

Measures Taken to Prevent a Recurrence of the Problem:

To eliminate recurrence, the following corrective measures were implemented:

- Replaced 229-7 belt 6/16/22
- Increased frequency of belt conveyor inspections
- Increased frequency to inspect the top of the silos for material accumulation; if material is present, initiate clean up

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9-Others

Division Code QA: _____

Monitoring and Permit Deviation Report - Part III

REPORT CERTIFICATION

SOURCE NAME: CEMEX Construction Materials South, LLC – Lyons Cement Plant

FACILITY IDENTIFICATION NUMBER: 013-0003

PERMIT NUMBER: 95OPBO082

All information for the Title V Semi-Annual Deviation Reports must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section I.B.38. This signed certification document must be packaged with the documents being submitted.

STATEMENT OF COMPLETENESS

I have reviewed the information being submitted in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this submittal are true, accurate and complete.

Please note that the Colorado Statutes state that any person who knowingly, as defined in Sub-Section 18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of Sub-Section 25-7 122.1, C.R.S.

Mr. Erasmo "Erik" Estrada Tovar

Printed or Typed Name

Plant Manager

Title



Signature of Responsible Official

8/01/2022

Date Signed

Note: Deviation reports shall be submitted to the Division at the address given in Appendix D of this permit. No copies need be sent to the U.S. EPA.