



August 1, 2024



Mr. Blue Parrish or Ms. Carissa Money
Colorado Department of Public Health and Environment
Air Pollution Control Division
Operating Permits Unit
APCD-SS-B1
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

Via Email

RE: Title V Semiannual Monitoring and Permit Deviation Report – 1/1/2024 to 6/30/2024
Title V Operating Permit 95OPBO082
CEMEX Lyons Cement Plant; Facility AIRS ID - CO 0130003

Dear Mr. Parrish and/or Ms. Money:

Enclosed is the Semiannual Monitoring and Permit Deviation Report for the reporting period January 1, 2024 through June 30, 2024 as required by Title V Operating Permit 95OPBO082 of the Lyons Cement Plant, Facility AIRS ID - CO 0130003.

Please contact me at (813) 525-3301 or through my email, kirill.smirnov@cemex.com, should you have questions or concerns about this submittal.

Sincerely,

A handwritten signature in black ink, appearing to read "Kirill Smirnov".

Kirill Smirnov
Environmental Specialist
Lyons Cement Plant

Cc: Mr. Dave Huber, CDPHE, via email
Ms. Gabi Hoefler, BCPH, via email

Semiannual Title V Monitoring and Permit Deviation Report

Operating Permit 95OPBO082

AIRS ID 013-0003

CEMEX Lyons Cement Plant

1/1/2024 to 6/30/2024

APPENDIX D

Notification Addresses

1. Air Pollution Control Division

Air Pollution Control Division
Operating Permits Unit
APCD-SS-B1
4300 Cherry Creek Drive S.
Denver, CO 80246-1530

ATTN: Blue Parrish – OR – Carissa Money

2. United States Environmental Protection Agency

Compliance Notifications:

Office of Enforcement, Compliance and Environmental Justice
Mail Code 8ENF-T
U.S. Environmental Protection Agency, Region VIII
1595 Wynkoop Street
Denver, CO 80202-1129

Note: Deviation reports shall be submitted to the Division at the address given in Appendix D of this permit. No copies need be sent to the U.S. EPA.

SUBMITTAL DEADLINES

First Semi-Annual Monitoring Period: March 1 – June 30

Subsequent Semi-Annual Monitoring Periods: July 1 – December 31, **January 1– June 30**

Semi-Annual Monitoring Reports: Due August 1, 2008 & February 1, 2009 & subsequent years

First Annual Compliance Period: March 1 - December 31

Monitoring and Permit Deviation Report - Part I

Operating Permit Unit ID	Unit Description	Deviations Noted During Period? ¹		Deviation Code ²	Malfunction/ Emergency Condition Reported During Period?	
		YES	NO		YES	NO
P017	Dowe Flats Quarry Fugitive Emission Sources & Lyons Quarry	X		9		X
P017	Dowe Flats Quarry – Point Source Emissions		X			X
P018	General Fugitive Emissions Requirements		X			X
P000	Raw Material Storage and Handling at Plant Site	X		9		X
P001	Primary Crusher (Plant Site)		X			X
P002	Raw Materials Drying		X			X
P003	Secondary Crushing, Screen, Silo, Belt Transfer	X		9		X
P004	Raw Materials Storage Silos		X			X
P005	Raw Mill Grinding		X			X
P006	Homogenizing and Blending	X		9		X
P007 & P008	Kiln Burning and Clinker Cooling and Transfer to Storage for Finish Mill		X			X
P009	Clinker and Gypsum/Additive Silos and Weigh Feeders (Storage and Transfer to Finish Mill)	X		9		X
P010	Sheltered (A-Frame) Clinker Storage and Reclaim	X		9		X
P015	Outdoor Clinker Piles and Handling	X		9		X
P011 & P012	Cement Finish Mill and Auxiliaries		X			X
P013	Cement Silos/Packhouse/Loadout		X			X
P014	Material Handling System – Load-In and Load-Out		X			X
P007A	Handling and Processing of CKD and Raw Material Waste Dust		X			X
P050	Cement Rail Car Unloading System		X			X
	Gasoline Storage Tank		X			X
	Cold Cleaner Solvent Vats		X			X
LIS-1	Lime storage silo		X			X
LIS-2	Lime weigh hopper		X			X
A-Pit Pump	Diesel fuel-fired engine, rated at 90 hp.		X			X
DF 6" Pump	Diesel fuel-fired engine, rated at 80 hp		X			X
DF 8" Pump	Diesel fuel-fired engine, rated at 84 hp		X			X
Kiln Engine	Natural gas-fired engine, rated at 230 hp (Emergency Engine)		X			X
Flood Engine	Diesel fuel-fired engine, rated at 99 hp (Emergency Engine)		X			X
	Insignificant Activities		X			X
	General Conditions		X			X

¹ See previous discussion regarding what is considered to be a deviation. Determination of whether or not a deviation has occurred shall be based on a reasonable inquiry using readily available information.

²Use the following entries as appropriate:

- | | |
|-------------------------|---|
| 1 = Standard: | When the requirement is an emission limit or standard |
| 2 = Process: | When the requirement is a production/process limit |
| 3 = Monitor: | When the requirement is monitoring |
| 4 = Test: | When the requirement is testing |
| 5 = Maintenance: | When required maintenance is not performed |
| 6 = Record: | When the requirement is recordkeeping |
| 7 = Report: | When the requirement is reporting |
| 8 = CAM: | A situation in which an excursion or exceedance as defined in 40 CFR Part 64 (the Compliance Assurance Monitoring (CAM) Rule) has occurred. |
| 9 = Other: | When the deviation is not covered by any of the above categories |

Monitoring and Permit Deviation Report - Part II 1/10/2024 Fugitive Dust/Housekeeping Issues

Is the deviation being claimed as an: Emergency _____ Malfunction _____ N/A XX

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation _____ XX _____

OPERATING PERMIT UNIT IDENTIFICATION: AIRs Pt. P024 Discharge of Primary-Crushed Raw Materials onto Open Stockpile and S009 - Front End Loader Activity

Operating Permit Condition Number Citation: Part II, Condition 1.6.4.

Explanation of Period of Deviation:

High winds picked up material from un-crusted stockpiles on the patio. Both water trucks were running to combat the winds. Additionally, material deliveries were not suspended until later in the day, and the winds took large amount of gypsum as it was unloaded near 6-belt, causing a large amount of dusting.

Duration (start/stop date & time): 1/10/2023 08:00 to 10:00

Actions Taken to Correct the Problem:

The water trucks were used to control fugitive emissions.

Measures Taken to Prevent a Recurrence of the Problem:

Reminded maintenance and production staff that water trucks need to be running according to the Fugitive Dust Plan and deliveries need to be suspended when winds pick up.

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9-Other

Division Code QA: _____

Monitoring and Permit Deviation Report - Part II 4/2/2024 – Dusting at the top of the Homogenization Silo.

Deviation being claimed as an: Emergency_____ Malfunction _____ N/A XX_____

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation XX_____

OPERATING PERMIT UNIT IDENTIFICATION: AIR pt 006: S014 - Homogenizing Silo

Operating Permit Condition Number Citation: Condition 22

Explanation of Period of Deviation:

Dust was observed originating at the top of the Homogenization Silo.

Duration (start/stop date & time): 4/2/2024, 13:00-13:30

Action Taken to Correct the Problem:

Homogenization Silo processes were paused to prevent dust.

Measures Taken to Prevent a Recurrence of the Problem:

Production conducted equipment checks inside the silo and cleaned out backed up transfer points.

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9 –Other

Division Code QA: _____

Monitoring and Permit Deviation Report - Part II 5/1/2024 – Fugitive Dust/Housekeeping Issues

Deviation being claimed as an: Emergency _____ Malfunction _____ N/A XX

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation XX

OPERATING PERMIT UNIT IDENTIFICATION: AIRs pt 025: Fugitive PM emissions from quarry activities

Operating Permit Condition Number Citation: Conditions 1.6.2.1 through 1.6.2.5

Explanation of Period of Deviation:

Dust was observed over Dowe Flats from atop the kiln stack. The environmental team reported the issue to the quarry superintendent, who reported that Claystone did not alert Lyons personnel that their water truck was down. As reclamation activities were not ceased while the water truck was not in operation, dust was created.

Duration (start/stop date & time): 5/3/2023 12:00 – 12:45

Action Taken to Correct the Problem:

Operations were ceased until water truck was able to water the roads and reclamation areas.

Measures Taken to Prevent a Recurrence of the Problem:

Another water truck was rented to ensure that at least one water truck is always running.

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9 Other

Division Code QA: _____

Monitoring and Permit Deviation Report - Part II 5/1/2024- 639-19 Clinker Reclaim Dust Collector

Is the deviation being claimed as an: Emergency _____ Malfunction _____ N/A XX

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation XX

OPERATING PERMIT UNIT IDENTIFICATION: AIRs pt 009 (P009): S021 – Top of A Frame (belt 529-30 to 529-63), S026, S027, S029, S030, S031 – Weigh Feeders 1, 2, 4, 5 and 6, S032 – Bottom of A-Frame Transfer, S024 - #2 Clinker Silo, S038 – Surge Bin, S035 – Discharge of 629-3 Belt, S039 - S041 – Finish Mill Weigh Feeders, S038 – Surge Bin , and S033 - Gypsum/Limestone from 529-31 belt to Silos

Operating Permit Condition Number Citation: Condition 19

Explanation of Period of Deviation:

Dust Collector dusting due to moisture inside system causing holes in housing.

Duration (start/stop date & time): 5/1/2024, 08:40 – 10:45

Actions Taken to Correct the Problem:

Dust collector operation was paused to assess the issue.

Measures Taken to Prevent a Recurrence of the Problem:

Holes in Dust collector housing were repaired to spec requirements.

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9-Other

Division Code QA: _____

Monitoring and Permit Deviation Report - Part II 6/23/2023 – Dust originating from A-frame

Is the deviation being claimed as an: Emergency _____ Malfunction _____ N/A **XX**

(For NSPS/MACT) Did the deviation occur during: Startup _____ Shutdown _____ Malfunction _____
Normal Operation XX

OPERATING PERMIT UNIT IDENTIFICATION: P010 - Sheltered (A-Frame) Clinker Storage and Reclaim

Operating Permit Condition Number Citation: Condition 22.33

Explanation of Period of Deviation:

A neighbor complaint was forwarded by Gabi Hoefler of Boulder County on 6/25/2024. The complaint stated that dust was noticed by the A-frame around 19:45. Based on the reviewed footage, fugitive dust originated from the A-frame door, starting at approximately 19:25. During Kiln preheat on Sunday (6/23/24), the cooler baghouse transport screws were started to accommodate the kiln dust going into the cooler. A-frame was selected as the transport path.

During this time, both A-frame doors were open. As a result, a wind tunnel effect was created, and kiln dust dropping into the A-frame created visible fugitive dust.

Duration (start/stop date & time): 6/25/2023, 19:25 – 20:25

Actions Taken to Correct the Problem:

A-Frame doors were closed to prevent further dust escaping from the south door.

Measures Taken to Prevent a Recurrence of the Problem:

Production personnel has communicated the importance of keeping A-frame doors closed. The addition of a sensor that would alert the control room is being investigated.

Dates of Malfunction/Emergencies Reported (if applicable): N/A

Deviation Code: 9-Other **Division Code QA:** _____

Monitoring and Permit Deviation Report - Part III

REPORT CERTIFICATION

SOURCE NAME: CEMEX Construction Materials South, LLC – Lyons Cement Plant

FACILITY IDENTIFICATION NUMBER: 013-0003

PERMIT NUMBER: 95OPBO082

All information for the Title V Semi-Annual Deviation Reports must be certified by a responsible official as defined in Colorado Regulation No. 3, Part A, Section I.B.38. This signed certification document must be packaged with the documents being submitted.

STATEMENT OF COMPLETENESS

I have reviewed the information being submitted in its entirety and, based on information and belief formed after reasonable inquiry, I certify that the statements and information contained in this submittal are true, accurate and complete.


Please note that the Colorado Statutes state that any person who knowingly, as defined in Sub-Section 18-1-501(6), C.R.S., makes any false material statement, representation, or certification in this document is guilty of a misdemeanor and may be punished in accordance with the provisions of Sub-Section 25-7 122.1, C.R.S.

Mr. Bradley A. Evans

Plant Manager

Printed or Typed Name

Title


Signature of Responsible Official

8-1-24
Date Signed

Note: Deviation reports shall be submitted to the Division at the address given in Appendix D of this permit. No copies need be sent to the U.S. EPA.