

Key Punch Data:	County		Source		Emission		Action		Date			Agency/		
	Number		Nr		Point #		Ty		Mo	Day	Yr	Indiv. ID		
Line 1	1	01	1	01	1	01	1	01	1	1	1	1	1	1
	1	3	4	7	8	12	13	15	16	18	52	54	59	66

Compliance Status

Line 2 (Dup. cols. 1-15 from Line 1)

16	18	78	80
----	----	----	----

(NOTE: Columns not shown must be left blank)
(Do not punch Line 2 if column 78 is blank)

Company: Martin Marietta Cement
 Site Location: Lyons CO
 Contact Person: Roy Cook, Process Manager
 Telephone No.: 534-4206

Inspected by: G. Mathews
 County: Boulder
 Time: 11:30-12:30
 EIS Update: No

Inspection: Routine ☒ Complaint ☐ FA ☐

2.25 Hrs.* Permit No. C-12,444-1

Emission Points Subject to NSPS: NA

- At time of regular annual inspection, #3 limestone dryer was out of operation. This inspection was arranged to inspect this point only and to provide John Wells, EPA Reg. & Director, and Kerry Klaugh, administrative ass't, an opportunity to observe an air pollution control field inspection. Also present were Bryan Miller, BCHD Env. Health director, and Rick Hay and Win Franklin, supervisors.
- Point is in opacity compliance - 0% Opacity. With regard to 10/18/83 letter from APCD, Martin-Marietta is now in the process of deciding whether C-12,444-1 should be for natural gas only and MMC is gathering fuel consumption and product rate data. A meeting to discuss offsets will be arranged with the MMC engineer who prepared the original permit application.
- The clinker cooler baghouses have been both ~~outfitted~~ ^{replaced} with new Gortex ~~bag~~ bags. Mr. Cook said that hot clinker will not have to be dropped into open storage space unless

Martin-Marietta Cement

November 2, 1983 Inspection Report continued

an upset condition occurs. Emission points from coolers were w/in opacity compliance at time of insp.

4. A-frame. North door is kept closed all the time, A dust curtain is ordered for south door.
5. At the time of inspection, the conveyor next to the limestone dryer baghouse was puffing. Mr. Cook speculated that the vent line was plugged. Unless plug is moist, the problem can be easily fixed by rapping with a hammer.
6. Status: Not in compliance due to outstanding items under C-12,444-1 permit and other points outlined in 10/12/83 letter
7. Time: Travel: 0.75 hrs.
 Inspection: 1.00
 Write-up: 0.50
 2.25 hrs.

NOV 13 1983
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT


ANALYTICAL REPORT OF VISIBLE EMISSION

OBSERVATION
LOCATION

COMPANY Martin Marietta Cement DATE 11/2/83
ADDRESS OF SOURCE Lyons Colorado
City Street County AQCR
STACK NAME limestone dryer
BACKGROUND SKY CONDITION cloudy - overcast
RELATIVE HUMIDITY _____ % PSYC. _____ WEATHER BUREAU _____ AIR TEMP. not 60°F °F
WIND SPEED calm WIND DIRECTION (From) NA
PLUME CHARACTERISTICS (Color, etc.) white
STACK HEIGHT ~ 30' Feet OBSERVER'S LOCATION ~ 50' Feet South of Stack
WET PLUME or DRY PLUME: (If WET, estimate the breakpoint distance from the stack)

CLOCK TIME	0	15	30	45
1146	0	-	-	-
1147	01	0	0	0
1148	02	0	0	0
1149	03	0	0	0
1150	04	0	0	0
1151	05	0	-	0
1152	06	0	0	0
	07			
	08			
	09			
	10			
	11			
	12			
	13			
	14			
	15			
	16			
	17			
	18			
	19			
	20			
	21			
	22			
	23			
	24			
	25			
	26			
	27			
	28			
	29			

SKETCH: Include 1) Wind Direction; 2) Sun Position; 3) Observer Position;
4) Approximate Location of stack; 5) North Arrow.
If more than one stack is located at the plant site
specifically identify the stack being read. Include remarks.



RECEIVED

DEC 9 '83

AIR POLLUTION
CONTROL DIVISION

OBSERVER: _____ DATE _____
PERSONS PRESENT DURING THE EVALUATION:

Name: Geo. Mathews
Title: Coordinator

SIGNATURES: Duplicate of this Analytical Report Given To

Name:

Title:

Date:

Time:

Signature: