



COLORADO DIVISION OF MINERALS AND GEOLOGY
MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567



The Division of Minerals and Geology has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance of the mining operation with the permit and the regulations of the Mined Land Reclamation Board. The report notes 1) Areas of successful compliance; 2) Problems and suggested corrective actions and/or 3) Possible violations to be considered for possible enforcement action by the Mined Land Reclamation Board. OPERATORS SHOULD READ THIS REPORT CAREFULLY BECAUSE IT MAY REQUIRE CORRECTIVE ACTION AND/OR RESPONSES TO THE DIVISION IN ORDER TO AVOID CONSIDERATION OF POSSIBLE ENFORCEMENT ACTION BY THE MINED LAND RECLAMATION BOARD.

MINE NAME: Larimer County Quarry OPERATOR: Southdown Inc.
COUNTY: Larimer MINERAL: Limestone TYPE OF OPERATION: open 112
INSPECTOR(S): Christina L. Kamnikar *Christina L. Kamnikar*
MINE ID # OR PROSPECTING ID #: M-77-341
INSPECTION DATE 05/01/97 DATE OF COMPLAINT NA
INSPECTOR'S INITIALS CLK TIME OF DAY (MILITARY) 10:00 AM
INSPECTION TYPE CODE⁽¹⁾ SI POST INSP. CONTACTS⁽²⁾ NO
JOINT INSP. AGENCY CODE⁽²⁾ NO REASON FOR INSP. CODE⁽³⁾ IE
WEATHER CODE⁽⁴⁾ CL OP. REP. PRESENT John Lohr, Southdown Inc.

1. INSPECTION TYPE CODE - [CL-IN: IL=Illegal Operation, MI=Monitoring, MP=Mineral Prospect, SI=Surety-related, PR=Pre-operation]
2. POST INSPECTION CONTACTS AND JOINT INSPECTION AGENCY CODE - [CL-AG: NO=None, BL=BLM, CH=Colo. Dept. Health, CL=Land Board, CT=Citizen, CW=Wildlife, FS=Forest Service, HW=Hwy. Dept., LG=Local Government, SE=State Engr.]
3. REASON FOR INSPECTION CODE - [CL-RS: AG=Other Agency Request, CT=Citizen Complaint, IE=Normal I&E Program, HP=High Priority, PY=Priority]
4. WEATHER CODE - [CL-WE: CL=Cloudy, CR=Clear, IN=Inclement - prevented inspection, RN=Raining, SN=Snowing, WD=Windy]

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. IF PB OR PV IS INDICATED, YOU SHOULD READ THE FOLLOWING PAGES CAREFULLY IN ORDER TO ASSURE COMPLIANCE WITH THE TERMS OF YOUR PERMIT AND APPLICABLE RULES AND REGULATIONS. If PV is indicated, you will be notified under separate cover when the Mined Land reclamation Board will consider possible enforcement action.

GENERAL INSPECTION TOPICS

(AR) RECORDS	<u>Y</u>	(FN) FINANCIAL WARRANTY . . .	<u>Y</u>	(RD) ROADS	<u>Y</u>
(HB) HYDROLOGIC BALANCE . . .	<u>Y</u>	(BG) BACKFILL & GRADING . . .	<u>Y</u>	(EX) EXPLOSIVES . . .	<u>NA</u>
(PW) PROCESSING WASTE/TAILINGS	<u>NA</u>	(SF) PROCESSING FACILITIES	<u>NA</u>	(TS) TOPSOIL	<u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE	<u>Y</u>	(FW) FISH & WILDLIFE	<u>Y</u>	(RV) REVEGETATION . . .	<u>Y</u>
(SM) SIGNS AND MARKERS	<u>Y</u>	(SP) STORM WATER MGT PLAN . . .	<u>Y</u>	(SB) COMPLETE INSP . . .	<u>Y</u>
(ES) OVERBURDEN/DEV. WASTE . . .	<u>Y</u>	(SC) EROSION/SEDIMENTATION	<u>Y</u>	(RS) RECL PLAN/COMP	<u>Y</u>
(AT) ACID OR TOXIC MATERIALS . .	<u>NA</u>	(OD) OFF-SITE DAMAGE	<u>Y</u>	(ST) STIPULATIONS . . .	<u>NA</u>

Y = Inspected and Found in Compliance
Inspected and Problems Noted

N = Not Inspected

PV = Inspected and Possible Violations Noted

NA = Not Applicable

PB =

WHITE - PUBLIC FILE

YELLOW - OPERATOR

PINK - CORRESPONDENCE FILE

MINE ID # OR PROSPECTING ID #
INSPECTION DATE 05/01/97

M-77-341

INSPECTOR'S INITIALS CLK

OBSERVATIONS

The following observations were made during a succession of operator bond inspection of this 196 acre 112 site.

1. All of the grading, with the exception of one 30' high, 100' long 1:1 scarp, has been completed. The scarp will be backfilled as soon as possible. The rest of the grading varies from 2H:1V to 3H:1V, and is consistent with the surrounding landscape.

2. Topsoil is in the process of being replaced on approximately 40 acres. For 12 acres of this (west excavation area), the topsoil was stored at the top of the slope, less than 100' away from the area to be covered. For the other 28 acres (south excavation area), the topsoil was stored some distance away, and the exact distance will be calculated using the maps of the haul roads.

3. An equipment and recycle yard of approximately 7 acres is currently in use at the site. The metals and excess materials will need to be removed prior to the site's release.

4. The rest of the site is undisturbed or has reached such a state of reclamation as to be indistinguishable from the surrounding landscape.

5. A sign with the site name and permit number was posted at the entrance to the site, and the boundaries are marked both by fence lines and natural boundaries (creeks, ridges, etc.). According to the 1996 Annual Report Map, Southdown was still inside the boundaries when they mined down the edge of the western ridge. Any extension of the mining beyond its current limits would take the company out of the permit area.

The bond will be recalculated taking existing conditions into account, and the lack of future excavation planned, within two weeks.

I & E Contact Address

NAME John Lohr
OPERATOR Southdown Inc.
STREET P.O. Box 529
CITY/STATE/ZIP Lyons, CO 80504

cc: Carl B. Mount, DMG

- ☐ CE
- ☐ BL
- ☐ FS
- ☐ HW
- ☐ HMWMD (CH)
- ☐ SE
- ☐ WQCD (CH)
- ☐ OTHER

MINE ID # OR PROSPECTING ID #
INSPECTION DATE 05/01/97

M-77-341

INSPECTOR'S INITIALS CLK

The following problems (PB) and/or possible violations (PV) (and suggested corrective actions) were identified during this inspection. The problems should be corrected by the dates given, or they will become possible violations. The possible violations should be corrected by the dates given to reduce their severity when considered by the Mined Land Reclamation Board. The inspector noted on the previous page should be notified of all corrective actions taken.

There are no problems noted at this time.