



Richard D. Lamm
Governor

DEPARTMENT OF NATURAL RESOURCES
David H. Getches, Executive Director

MINED LAND RECLAMATION DIVISION
DAVID C. SHELTON, Director



NOTICE OF INSPECTION
AND
INSPECTION REPORT

DATE OF INSPECTION: January 30, 1986
OPERATOR CONTACT: Marvin Berg
NAME OF OPERATOR: Southwestern Cement Enterprises, Inc.
ADDRESS: P.O. Box 529
Lyons, Colorado 80540
FILE NO.: M-77-341
MINE: Larimer County Quarry
COUNTY: Larimer
ACRES PERMITTED: 196
INSPECTOR(S): Patricia Martinek, James McArdle, Carl Mount

(Please note the instructions indicated by an X below)

- ☒ No problems noted at time of inspection. As a reminder, be sure to file your Annual Report or Notice of Intent to Continue by the Permit Anniversary Date.
- ☐ Possible problem(s) - Note recommendation(s) below to avoid further complications or possible violation(s) at the time of the next inspection.
- ☐ Possible violation(s) - Complete recommendation(s) below and reply to the Division by _____ to defer consideration by the Mined Land Reclamation Board.
- ☐ Possible violation(s) require MLR Board consideration on date specified under separate cover.

(Continued on page 2)

INSPECTION REPORT - PAGE 2
FILE NO. M-77-341
DATE: January 30, 1986

OBSERVATIONS OF IMPORTANCE:

1. Operator continues to do an excellent job of reclaiming this site. Final grades, topography, and revegetation densities are consistent with the permit stipulations. Areas E and F (?) appear to be sparsely vegetated; however, new germination is beginning to show.
2. The overall geometry of the quarry operation generally appears to be consistent with that in the annual report. However, the annual report map is impossible to use in defining overall topography, permit boundaries, establishing quarry and reclaimed area boundaries, and defining roads, utility lines, and equipment storage areas.
3. Annual report and fees are currently up-to-date.
4. On January 7, 1986, we received a phone call from local residents stating that structural damage to their homes was resulting from blasting at the Larimer County Quarry. Please be advised that a letter from them is being sent to you and to the Division regarding this matter.

RECOMMENDATIONS:

1. Please submit a more useable map with your next annual report in July, 1986. Please clearly portray the permit boundaries, overall topography, utility lines, roads, and equipment storage areas, as well as quarrying and reclaimed area boundaries.

/tmb
7133F

INSPECTION REPORT - PAGE 2
FILE NO. M-77-341
DATE: September 13, 1985

OBSERVATIONS OF IMPORTANCE:

1. Area on extreme east side is well vegetated.
2. Operator is starting to re-establish drainage way on east side progressing west.
3. Pit is now starting to turn northwest with mining directly west has ceased.
4. Depth of pit is about 100+ feet.
5. Area on east side to be resloped and revegetated this fall adjacent to previously reclaimed areas.
6. Financial Warranty of \$28,000.00 should be adequate for this site.
7. Operator is continuing to do an excellent job at this site.
8. Slides 12: Reclaimed Drainage
 13-15: Pit Area Overview Looking North
 16-18: Looking South in New Area to be Mined and Old Area
 already Mined in Background

PVOC/mis
3390F