## Alarm Help - MV SERIES -



ALARM ADDRESS	A27.3	ALARM NO.	1303
OP. MESSAGE	NO CONFIRM OF APC POS.1		
Related Signal	Input: X16.2 (154APC) •		
CAUSE	Pellet 1 in position not reached		
ACTION	P1 sensor X16.2 not detected after 1.check X16.2 signal.	er pallet swing fi	inish:
	2.hydraulic pressure.		
	3.adjust sensor detect distance.		