## Alarm Help - MV SERIES -



ALARM ADDRESS	A24.4	ALARM NO.	2092
OP. MESSAGE	SPINDLE SPEED OVERRIDE PARITY CHECKING ERROR.		
	CHECKING WIRING IN PANEL UNIT.		
Related Signal	Input: X36.6 , X36.7 , X37.0 , X37.1 , X37.2(MV154/154APC/MV204/184C) -		
CAUSE	Spindle override wiring signal is missed •		
ACTION	Take out panel to examine the w	viring as attache	ed circuit diagram •