Alarm Help - MV SERIES -



ALARM ADDRESS	A24.2	ALARM NO.	2090
OP. MESSAGE	JOG FEEDRATE OVERRIDE PARITY CHECKING ERROR.		
	CHECKING THE WIRING IN PANEL UNIT.		
Related Signal	Input: X36.0 , X36.1 , X36.2 , X36.3 , X36.4 (MV154/154APC/MV204/184C) •		
CAUSE	JOG feed rate rotary switch wiring missed signal •		
ACTION	Take out panel to examine the wiring as attached circuit diagram •		