中国民用航空总局



CAAC 适 航 指 令

AIRWORTHINESS DIRECTIVE

本指令根据中国民用航空规章《民用航空器适航指令规定》(CCAR-39)颁发,内容涉及飞行安全,是强制性措施。如不按规定完成,有关航空器将不再适航。

编号: CAD1996-C650-01

修正案号: 39-1569

一. 标题: 改换主起落架轮胎

二. 适用范围:

在主起落架上装有件号(P/N)028-520-1(22X5.75-12/10PR),序号如下的轮胎的CESSNA 650(CITATION VI)型飞机,但不限于该型飞机:

| 4279N00339 | 4279N00340 | 4279N00341 | |
|------------|------------|------------|--|
| 4279N00342 | | | |
| 4279N00343 | 4279N00597 | 4279N00598 | |
| 4279N00599 | | | |
| 4279N00600 | 4279N00601 | 4280N00075 | |
| 4280N00199 | | | |
| 4280N00200 | 4280N00201 | 4280N00203 | |
| 4280N00204 | | | |
| 4280N00205 | 4280N00206 | 4280N00360 | |
| 4280N00361 | | | |
| 4282N00352 | 4283N00099 | 4283N00100 | |
| 4283N00101 | | | |
| 4283N00102 | 4283N00200 | 4283N00201 | |
| 4283N00202 | | | |
| 4283N00453 | 4283N00454 | 4283N00455 | |
| 4283N00456 | | | |
| 4284N00612 | 4284N00613 | 4284N00614 | |

| CAD1996-C650-01 | / 39-1569 |
|-----------------|-----------|
| | |

| 4284N00615 | | |
|--------------------------|-------------|-------------|
| 4284N00616 | 4285N00100 | 4285N00101 |
| 4285N00102 | 12001100100 | 12001100101 |
| 4285N00103 | 4285N00104 | 4285N00105 |
| 4285N00106 | | |
| 4285N00107 | 4285N00108 | 4285N00347 |
| 4285N00348 | | |
| 4285N00349 | 4285N00353 | 4285N00354 |
| 4285N00355 | | |
| 4285N00356 | 4285N00608 | 4285N00609 |
| 4286N00103 | | |
| 4286N00104 | 4286N00105 | 4286N00106 |
| 4286N00442 | | |
| 4286N00443 | 4286N00444 | 4286N00445 |
| 4286N00446 | | |
| 4286N00447 | 4286N00448 | 4286N00449 |
| 4286N00450 | | |
| 4286N00600 | 4286N00601 | 4286N00602 |
| 4286N00602 | | |
| 4286N00604 | 4286N00605 | 4286N00606 |
| 4286N00608 | | |
| 4286N00609 | 4287N00088 | 4287N00089 |
| 4287N00090 | 400=340000 | 400=170000 |
| 4287N00091 | 4287N00092 | 4287N00093 |
| 4287N00094 | 40051100000 | 40051100005 |
| 4287N00095 | 4287N00096 | 4287N00097 |
| 4287N00357 | 40071100050 | 40071100960 |
| 4287N00358 | 4287N00359 | 4287N00360 |
| 4287N00361 | 4907N00969 | 4907N00964 |
| 4287N00362 | 4287N00363 | 4287N00364 |
| 4288N00118 4288N00119 | 4288N00120 | 4288N00121 |
| 4288N00302 | 4400NUU14U | 4400NUU141 |
| 4288N00302 4288N00303 | 4288N00304 | 4288N00305 |
| 4288N00306 | 4400NUU3U4 | 4400NU00U0 |
| 4400N00300 | | |

| / | _ | \sim | 1 | _ | | \sim |
|---|-----|--------|-----|---|----|--------|
| / | - 4 | u | -1 | ` | h | u |
| / | | | - 1 | J | ν, | , |

| 4288N00307 | 4290N00111 | 4290N00113 |
|------------|------------|------------|
| 4290N00114 | | |
| 4290N00115 | 4290N00116 | 4290N00117 |
| 4290N00355 | | |
| 4290N00356 | 4290N00606 | 4290N00607 |
| 4290N00608 | | |
| 4290N00609 | 4290N00610 | 4290N00611 |
| 4290N00612 | | |
| 4291N00082 | 4291N00083 | 4291N00084 |
| 4291N00085 | | |
| 4291N00086 | 4291N00087 | 4291N00088 |
| 4291N00089 | | |
| 4291N00091 | 4291N00273 | 4291N00274 |
| 4291N00275 | | |
| 4291N00276 | 4291N00277 | 4291N00278 |
| 4291N00620 | | |
| 4291N00621 | | |

三. 参考文件:

FAA AD 95-24-10 39-9500

四. 原因、措施和规定

为防止飞机在着陆动作时,由于轮胎

(P/N) 028-520-1 (22X5. 75-12/10PR) 损坏而失去控制, 要求完成下述工作, 除非在本指令生效前已完成1995年11月21日的重要信函AD 95-24-20 PL所要求的工作:

- 1. 在本指令生效后下次飞行前,将本指令"适用范围"中所规定的 所有(P/N)028-520-1(22X5.75-12/10PR)轮胎改换成经FAA批准使用的 轮胎.
- 2. 完成本指令可采取能保证安全的替代方法或调整完成的时间,但必须得到适航当局的批准.
- 五. 生效日期: 1996年2月28日
- 六. 颁发日期: 1996年2月27日

七. 联系人: 邵仁明

民航华北管理局适航处

64592341