



PROCEDURE FOR SCALE CALIBRATION VERIFICATION

Note:

Scale calibration verification should be performed daily when operating in a production room. Scales are assigned to production rooms. Ensure the scale asset tag corresponds to the production room number. If multiple scales will be used in the same production room, notify QA for approval.

Information:

Scale calibration verification uses a three-point procedure consisting of minimum, target, and maximum weights in that order. Weights are specified on Forms 417-01 through 417-05. Place the weights at the center of the scale and at two opposing corners. Ensure the scale is zeroed before placing any weights.

Procedure:

Zero the scale before beginning the test. Place the minimum weight in the center of the scale and record the result. Without removing the first weight, add the second weight(s) on both sides of the first weight(s) to reach the target weight and record the result. Add the third weight(s) on the sides of the center weight to reach maximum weight and record the result. The zero may be checked between each location to see that it has not changed. If necessary, the scale can be zeroed in between each test. After recording the results, a QA/QC personnel must verify the documentation before production starts.

Key:

For weight placement use either points:

