



Aviation Investigation Final Report

Location: Paris, Kentucky Accident Number: ERA23LA105

Date & Time: January 5, 2023, 16:04 Local Registration: N6111W

Aircraft: Piper PA-28-140 Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 1 Minor, 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot and two passengers were departing from a 2,800-ft-long turf runway and reported that prior to initiating the takeoff the wind was light and variable. During the initial climb after takeoff, and once the airplane had cleared a ridge and trees that ran parallel to the runway, the pilot reported that there was a "sudden windshear that caused a reduction in lift." The pilot reduced the airplane's pitch attitude in an attempt to regain lift, but the airplane continued to descend. The pilot was unable to arrest the descent and the airplane subsequently impacted the ground. The pilot reported that there were no mechanical malfunctions or failures of the airplane that would have precluded normal operation. The automated weather observation at an airport 9 miles away noted wind at 10 knots, with no gusts or other convective activity described.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of control after encountering changing wind conditions during the initial climb, which resulted in descent and collision with terrain.

Findings

Personnel issues	Aircraft control - Pilot
Personner issues	All Clart Collinor - Pilot

Aircraft Angle of attack - Not attained/maintained

Environmental issues Variable wind - Response/compensation

Page 2 of 6 ERA23LA105

Factual Information

History of Flight

Initial climb Other weather encounter

Initial climb Loss of control in flight (Defining event)

Uncontrolled descent Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Airline transport; Flight instructor	Age:	36,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	September 9, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	6000 hours (Total, all aircraft), 640 hours (Total, this make and model), 3177 hours (Pilot In Command, all aircraft), 188 hours (Last 90 days, all aircraft)		

Passenger Information

Certificate:		Age:	Male
Airplane Rating(s):		Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	Lap only
Instrument Rating(s):		Second Pilot Present:	Yes
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Page 3 of 6 ERA23LA105

Passenger Information

Certificate:	A = 0.	Mala	
Certificate:	Age:	Male	
Airplane Rating(s):	Seat Occupied:	Rear	
Other Aircraft Rating(s):	Restraint Used:	Lap only	
Instrument Rating(s):	Second Pilot Present:	Yes	
Instructor Rating(s):	Toxicology Performed:		
Medical Certification:	Last FAA Medical Exam:		
Occupational Pilot: UNK	Last Flight Review or Equivale	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N6111W
Model/Series:	PA-28-140	Aircraft Category:	Airplane
Year of Manufacture:	1964	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	28-20126
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	May 13, 2022 Annual	Certified Max Gross Wt.:	2150 lbs
Time Since Last Inspection:	30 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2825 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-320-E2A
Registered Owner:	On file	Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 4 of 6 ERA23LA105

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	27K,890 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	16:15 Local	Direction from Accident Site:	280°
Lowest Cloud Condition:	Unknown	Visibility	10 miles
Lowest Ceiling:	Overcast / 5000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.93 inches Hg	Temperature/Dew Point:	8°C / 0°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Paris, KY	Type of Flight Plan Filed:	None
Destination:	Waddy , KY (3KY9)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	WILD BLUE 31KY	Runway Surface Type:	Grass/turf
Airport Elevation:	890 ft msl	Runway Surface Condition:	Unknown
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	2800 ft / 75 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 2 None	Latitude, Longitude:	38.2098,-84.253(est)

Page 5 of 6 ERA23LA105

Administrative Information

Investigator In Charge (IIC):Alleyne, EricAdditional Participating Persons:Sean B. Smith; FAA/FSDO; Louisville , KYOriginal Publish Date:June 15, 2023Last Revision Date:Investigation Class:Investigation Class:Class 4Note:The NTSB did not travel to the scene of this accident.Investigation Docket:https://data.ntsb.gov/Docket?ProjectID=106552

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ERA23LA105