



Aviation Investigation Final Report

Location: Emmett, Idaho Accident Number: WPR23LA265

Date & Time: July 8, 2023, 13:52 Local Registration: N74778

Aircraft: ROBINSON HELICOPTER R22
BETA Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 2 Minor

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor reported that he was demonstrating a turning autorotation to his student. The instructor entered the glide, turned, and kept the engine and rotor RPM gauges in the green arc, while maintaining an airspeed of about 55 knots. He increased the throttle setting and raised the collective lever as the helicopter descended through 200 ft AGL, however, the rotor RPMs fell below the green arc. The instructor made the decision to continue the autorotation with ground contact and applied aft cyclic to reduce the decent rate. The helicopter landed hard and nosed over onto its right side, resulting in substantial damage to the tailboom and tail rotor assembly. The instructor reported that there were no preaccident mechanical malfunctions or failures that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The instructor's failure to maintain airspeed during a simulated turning autorotation, which resulted in a hard landing.

Findings

Personnel issues	Aircraft control - Instructor/check pilot
Aircraft	Airspeed - Not attained/maintained

Page 2 of 6 WPR23LA265

Factual Information

History of Flight

Maneuvering	Loss of control in flight (Defining event)
Autorotation	Hard landing

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	25,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	3-point
Instrument Rating(s):	Helicopter	Second Pilot Present:	Yes
Instructor Rating(s):	Instrument helicopter	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	December 27, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 27, 2023
Flight Time:	571.6 hours (Total, all aircraft), 391.3 hours (Total, this make and model), 523 hours (Pilot In Command, all aircraft), 228.8 hours (Last 90 days, all aircraft), 67.8 hours (Last 30 days, all aircraft), 1.5 hours (Last 24 hours, all aircraft)		

Student pilot Information

otaucité bilot information			
Certificate:	Student	Age:	Male
Airplane Rating(s):	None	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	April 12, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	70.4 hours (Total, all aircraft), 70.4 hours (Total, this make and model), 1.4 hours (Pilot In Command, all aircraft), 42.3 hours (Last 90 days, all aircraft), 17.1 hours (Last 30 days, all aircraft)		

Page 3 of 6 WPR23LA265

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER	Registration:	N74778
Model/Series:	R22 BETA	Aircraft Category:	Helicopter
Year of Manufacture:	2005	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3968
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	June 14, 2023 100 hour	Certified Max Gross Wt.:	1370 lbs
Time Since Last Inspection:	58.75 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	7283.75 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	0-360-J2A
Registered Owner:	On file	Rated Power:	145 Horsepower
Operator:	On file	Operating Certificate(s) Held:	Rotorcraft external load (133), On-demand air taxi (135), Pilot school (141)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KEUL,2429 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	13:56 Local	Direction from Accident Site:	204°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/ Convective
Wind Direction:		Turbulence Severity Forecast/Actual:	/ Light
Altimeter Setting:	29.87 inches Hg	Temperature/Dew Point:	31°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Caldwell, ID (KEUL)	Type of Flight Plan Filed:	Company VFR
Destination:	Caldwell, ID (KEUL)	Type of Clearance:	None
Departure Time:	13:22 Local	Type of Airspace:	Class G

Page 4 of 6 WPR23LA265

Wreckage and Impact Information

Crew Injuries:	2 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	43.794444,-116.54444

Page 5 of 6 WPR23LA265

Administrative Information

Investigator In Charge (IIC):	Blocher, Kristyn
Additional Participating Persons:	Jeremy Blanford; Federal Aviation Administration; Boise, ID
Original Publish Date:	November 2, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192583

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR23LA265