

Sensor A1, $T = 20\text{ C}$, $v_{\text{over}} = 7\text{ V}$ - Decreasing and disappearing uniformly, $L > 1000$

