

Sensor A1, T = 20 C, $v_{\text{over}} = 7$ V - Decreasing and disappearing fluctuating, L>1000

