D1 and D2 will clamp the voltage and blow the fuses on the +/−15V supply rails if the polarity is reversed. The power supply should have fuses at the outputs, or current limiting.



C13, C16 and C25 block DC input component from the amplifiers and should usually be bypassed with 0Ω.



























TITLE: piezo_amplifier	
Document Number:	REV:
Date: not saved!	Sheet: 1/1