1 2 3


Project: DM0260 Current Revision: R4M2E2


DM0260 Revision History:

Date	Revision	Reason for Change	Changes Implemented
12/30/2020	BG0250TG-> R0M0E0	ESD protection FFC connector stronger mechanics Outdated stackup	1) Added protection diodes to MIPI lines 2) Changed FFC with Molex 505278 series 3) Standarized 4L stackup
02/12/2020	R0M0E0 -> R1M1E1	Make FFC connectors type and pinout ArduCam standard so that camera modules will be compatible with MJ1090FC Library and components not common w/ LaxonisMaster and some has bigger size footprint than needed	JuChanged FFC connectors to Ardu Cam standard pinout, updated all connections to the conenctors. CBA can be connected with same side 26pin FFC to DM 100 FFC 2). Updated all componets using LuxonisMaster libraries 3). Beamoved unecessary components from design (10k pull-ups on LDO enable connected directly) made downsizing of footprints for easier layout
02/12/2020	DM0250_R1M1E1 -> DM0260_R0M0E0	1) Add support for 33-pin standard FPC connector from Arducam 2) Add support for multiple cameras by option to change the core voltage	Used 33-pin standard FPC connector for CCM With populating either R4 or R5 you can select 1V05 or 1V2 core voltage respectively.
02/12/2020	DM0260_R0M0E0 -> DM0260_R1M0E0	Correct the error because of unused pads Add GND vias reducing the current loops	Corrected added pads on top/bottom layer Added GND vias
11/04/2020	DM0260_R1M0E0 -> DM0260_R2M1E1	1) Rotate text for 180 deg for better readability 2) Add holes for M12 camera holder (PV111-577) 3) Change the logo from old one to new one	1) Rosteed text for 180 deg for better readability 2) Added holes for M12 camera holder (PY111-577) 3) Changed the logo from old one to new one
06/29/2023	DM0260_R2M1E1 -> DM0260_R3M1E2	Missing EEPROM.	Added EEPROM and connected CAM_RST to change address of EEPROM.
08/07/2023	DM0260_R3M1E2-> DM0260_R4M1E2	missing pads on TOP and BOTTOM on GND vias, manufacturing problem.	Restoring removed unused pads.
10/11/2023	DM0260_R4M1E2 -> DM0260_R4M2E2	Missing holes for 20mm pitch CCM	Changing 2 mounting holes with pitch of 18 mm to slot to support 18 and 20mm mounting pitch.


Title DM	0260		Luxonis Holding 1925 Harmony Park Drive	G			
Size: Tabl	oid Number: D0000999	Revision:R4M2E2	Westminster, CO 80234	Cannot open file C:\Users\BrianLuxonis\			
Date: 26.0	. 2024 Time: 16:09:04	Sheet 1 of 3	United States	11			

1 2 3 4 5









- AVDD rising can occur before or after DOVDD rising as long as they are rising before XSHUTDOWN rising
 XSHUTDOWN is pulled up after AVDD and DOVDD are stable
 DVDD rises after DOVDD, but before XSHUTDOWN is pulled high

Title DM0260				Luxonis Holding 1925 Harmony Park Drive	G	
Size:	Tabloid	Number: D0000999	Revision:R4M2E2	Westminster, CO 80234	Cannot open file C:\Users\BrianLuxonis\	
Date:	26.06.202	4 Time: 16:09:04	Sheet 2 of 3	United States	11	

