Project: BC2087 Current Revision: R2M1E2

BC2087 Revision History:

| Date | Revision | Reason for Change | Changes Implemented |
|-------------|---------------------------|--|--|
| 22/Aug/2022 | Iniital Release -> R0M0E0 | | |
| 17/01/2023 | ROMOEO -> RIMOEI | - Change the right camera to be connected to 12C3 not 12C0 as is at the moment Changed BXO INT and WAKE pins to IO42 and IO15 (MX) so that they are not on box pins on XB. FIRST absorbed to Manusceded to IO. FIRST absorbed to the state of the pins of the | - Moved right camera to I2CS - Changed pins to IO42 and IO15 (MX) - Changed PCIL, PERST to IO39 (MX) - Added right camera reset line to IO43 (MX) - Added a loader with I2C4/UAKT - Changed CIL, POST (MX) - Changed CIL, POST (MX) - Changed IO SMD pins - Connected PSYNC to IO46 (MX) and IO14 (KB) |
| | | | |
| | | | |
| | | | |

| Title | BC2087 | , | | Luxonis Holding 1925 Harmony Park Drive | |
|-------|------------|------------------|-----------------|--|--|
| Size: | Tabloid | Number: D2088000 | Revision:R2M1E2 | Westminster, CO 80234 | Cannot open file C:\Users\BrianLuxonis\ |
| Date: | 26/04/2023 | Time: 14:17:42 | Sheet 1 of 12 | United States | 14-14-14-14-14-14-14-14-14-14-14-14-14-1 |

1 2 3 4 5



























