



DEALER BEST PRACTICE SERIES

Tool for Blocking the 793 OHT Hoist Cylinder Rod

Maintenance and Repair Application Component Life Management Component Renewal (CRC) MARC Management

Tool for Blocking the 793 OHT Hoist Cylinder Rod.....0

1.0 Introduction1

2.0 Best Practice Description1

3.0 Implementation Steps2

4.0 Benefits3

5.0 Resources Required3

6.0 Supporting Attachments / References.....3

7.0 Related Best Practices.....4

8.0 Acknowledgements5

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

Hoist cylinders are essential for proper functioning of mining trucks. Due to the weight of these components lifting and handling are a high safety risk. When suspended the rod can come off the cylinder and cause an accident. Chains are used to retain the rod and reduce the risk. During the manipulation of this component, the risk for an accident is still present.

2.0 Best Practice Description

In search for safer working procedures, a tool has been designed in order to make the repairs easier and reduce risk. This consists of a clamping mechanism that retains the rod and cylinder while working on the component.



Figure 1

The tool is designed to be installed prior to removing the cylinder.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Tools for Blocking the 793 OHT Hoist Cylinder Rod

DATE
2/13/2015

CHG
NO
00

NUMBER
1212-1.11-1301



Figure 2

In figure 3, the tool assembly process is shown.



Figure 3

3.0 Implementation Steps

- Design and manufacture the tool shown.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Tools for Blocking the 793 OHT Hoist Cylinder Rod	DATE 2/13/2015	CHG NO 00	NUMBER 1212-1.11-1301

4.0 Benefits


- Reduce accident risk while performing maintenance and repairs on 793 trucks
- Improve efficiency of maintenance processes.
- Improve ergonomics for workers exposed to 793 truck repairs

5.0 Resources Required

The necessary elements in order to implement the Best Practice are:

- Workforce
- Materials (according to drawing)
- Fabrication Tools

6.0 Supporting Attachments / References



Stress Analysis


THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Tools for Blocking the 793 OHT Hoist Cylinder Rod

DATE
2/13/2015

CHG
NO
00

NUMBER
1212-1.11-1301



7.0 Related Best Practices

N/A

8.0 Acknowledgements

Name : Kaor Rojas
Title : PCR Supervisor
E-mail : kaor_rojas @gecolsa.com.co
Phone : +57 316-428-5924

Checked and written by:

Name : Ricardo Chegwin
Title : Technical manage
E-mail : ricardo_chegwin@ gecolsa.com.co

Special thanks to:
The Development and Engineering Area Team

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Tools for Blocking the 793 OHT Hoist Cylinder Rod

DATE
2/13/2015

CHG
NO
00

NUMBER
1212-1.11-1301