



C175 - Identification Tags for Engines that Require Thicker Integral Seals

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

C175 - Identification Tags for Engines that Require Thicker Integral Seals	0
1.0 Introduction	1
2.0 Best Practice Description.....	1
3.0 Implementation Steps	2
4.0 Benefits.....	2
5.0 Resources Required	3
6.0 Supporting Attachments / References	3
7.0 Related Best Practices	3
8.0 Acknowledgements.....	3

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

1.0 Introduction

C175 Engines that have the top deck milled at overhaul may require a thicker cylinder head integral seal than the standard seal (reference Reuse and Salvage Guideline SEBF9185 for this specification). This Best Practice describes a method to call attention to a field service person, or a CRC partial repair bay, to an engine requiring the thicker seal.

2.0 Best Practice Description

This Dealer has implemented a practice of affixing a stamped aluminum plate to each valve cover using epoxy on an engine that was milled under the specification. An additional plate is put next to the Component ID tag on the engine.

In this example, the plate reads:


ENGINE BLOCK REQUIRES
THICKER HEAD GASKETS
USE P/N 394-0295

RENO CRC



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

C175 ID Tags for Engines that Require Thicker Integral Seals	DATE 6/16/2016	CHG NO 00	NUMBER 1606-4.01-1439
--	-------------------	-----------------	--------------------------



Another example of a Dealer using decals for placement on the valve covers:



3.0 Implementation Steps

Have these plates made up, and add necessary processes to control documents as required.

4.0 Benefits

This practice ensures the correct seal is installed during a repair that involves removing the cylinder head, to eliminate oil leakage and potential engine damage.

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
C175 ID Tags for Engines that Require Thicker Integral Seals	DATE 6/16/2016	CHG NO 00	NUMBER 1606-4.01-1439

5.0 Resources Required

Minimal, as described above

6.0 Supporting Attachments / References

7.0 Related Best Practices

8.0 Acknowledgements

This Best Practice was developed at, and photos submitted, by:
Cashman CRC in Reno, NV
Matco CRC in Hermosillo, MX (decal)

This Best Practice was written by:
Bill Gallagher – Cat Global Mining
Gallagher_William_L@cat.com

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
C175 ID Tags for Engines that Require Thicker Integral Seals	DATE 6/16/2016	CHG NO 00	NUMBER 1606-4.01-1439