



MINING DEALER BEST PRACTICE

980H Steering Pump Maximum Angle Piston Torque Tool

Maintenance and
Repair

Application

Component Life
Management

Component
Renewal (CRC)

MARC
Management

980H Steering Pump Maximum Angle Piston Torque Tool....	1
1.0 Introduction	2
2.0 Best Practice Description	2
3.0 Implementation Steps.....	3
4.0 Benefits	3
5.0 Resources Required.....	3
6.0 Supporting Attachments / References.....	4
7.0 Related Best Practices	4
8.0 Acknowledgements	5

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

March 2021
4.03-210303-1

1.0 Introduction


During the revision process of the 980H Steering Pumps, there has been trouble both while removing and torqueing the pistons. While one of the two pistons in the Steering Pump could be disassembled thanks to hexagonal bolt gap, the other piston's grip point was not reliable. The tightening tool could damage the piston using this method.



2.0 Best Practice Description

During the revision process of the Steering Pump shown in the below image, the seal O-ring located under the pistons must be removed to replace it with a new one. Although an allen bolt hole is made in the design for disassembling the right piston, this hole is not available in the left piston. Tightening and loosening with the help of a wrench may cause to scratch and damage the part. With the help of the tool we have implemented, this process does not damage the part and can be easily adjusted to the desired torque value.

This piston must be removed by this point where it has the potential to cause damage to surface.



There is an allen bolt hole made in the design for disassembling

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
980H Steering Pump Maximum Angle Piston Torque Tool	DATE 3/3/2021	CHG NO 00	NUMBER 4.03-210303-1

3.0 Implementation Steps

1. Follow the assembly procedure as outlined in Specification media number UENR2001, section "Piston Pump (Steering)".
 - a. Place the tool over the maximum angle piston and engage the flat areas for tightening.
 - b. Torque the part properly, as specified in UENR2001. It is tightened more securely thanks to its full grip.



4.0 Benefits

It minimizes the risk of damage.

Torque can be adjusted more easily in tightening.

It provides easier working opportunity for the technician.

5.0 Resources Required


Material: 50 TL

Labor: 2 hours

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
980H Steering Pump Maximum Angle Piston Torque Tool	DATE 3/3/2021	CHG NO 00	NUMBER 4.03-210303-1

6.0 Supporting Attachments / References

980H Steering Pump Torque Tool Technical Drawing.pdf



Steering Pump Angle Piston Torque Tool.MP4

SIS2.0 Media Number reference: UENR2001, Piston Pump (Steering)

7.0 Related Best Practices

None

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

980H Steering Pump Maximum Angle Piston Torque Tool

DATE
3/3/2021

CHG
NO
00

NUMBER
4.03-210303-1

8.0 Acknowledgements

This Best Practice was written by:
Aycan ULU
CRC Workshop Engineer
Borusan Makina ve Güç Sistemleri

This Best Practice designed by:
Aycan ULU
CRC Workshop Engineer
Borusan Makina ve Güç Sistemleri

Project and Best practice supported by
Emre KARAHAN
CRC Gebze Leader
Borusan Makina ve Güç Sistemleri

Volkan YAYMAN
CRC Leader
Borusan Makina ve Güç Sistemleri

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
980H Steering Pump Maximum Angle Piston Torque Tool	DATE 3/3/2021	CHG NO 00	NUMBER 4.03-210303-1