



MINING DEALER BEST PRACTICE

Illumination in the PLC Cabinet - MD6640

**Maintenance and
Repair**

Application

**Component Life
Management**

**Component
Renewal (CRC)**

**MARC
Management**

Illumination in the PLC Cabinet – MD6640	1
1.0 Introduction.....	2
2.0 Best Practice Description	2
3.0 Implementation Steps.....	2
4.0 Benefits	3
5.0 Resources Required.....	4
6.0 Supporting Attachments / References.....	4
7.0 Related Best Practices	4
8.0 Acknowledgements	4

DISCLAIMER: The information and potential benefits included in this document are based upon information provided by one or more Cat® dealers, and such dealer(s) opinion of “Best Practices.” Caterpillar makes no representation or warranty about the information contained in this document or the products referenced herein. Caterpillar welcomes additional “Best Practice” recommendations from our dealer network.

August 2022
1.10-220825-1

1.0 Introduction

It is difficult to carry out maintenance/repairs in the PLC cabinet room due to the confined space, lack of access to sufficient lighting and trying to do repair while holding flashlights. Currently PLC cabinets do not have an internal light source; the PLC cabinet having its own light source would help mitigate the last two of three difficulties and would allow for more efficient and effective maintenance/repairs and inspections.

2.0 Best Practice Description

The Best Practice is the simple but effective illumination of the PLC cabinet using a 24V Headlight to provide sufficient lighting supporting more efficient and effective maintenance/repair work and inspections.

With commonly available parts and a little manpower, sufficient lighting can be provided for the PLC cabinet. Implementation of the Best Practice can be done easily during a PM to minimize additional downtime of the machine.

3.0 Implementation Steps

A. Install the 24V Headlight

The 24V Headlight – PN 487-7586 - was chosen as it was a part commonly used on site. Each dealer can choose the appropriate option/part number for their site. The cable should be appropriately routed and tied down.



B. Install the switch in the cabinet door.

The switch – PN 530-6765 - was chosen as it was a part commonly used on site. Each dealer can choose the appropriate option/part number for their site.

C. Direct power from PS1 (24V source).

Power can be taken direction from the PS1 (24V source).

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR			
Illumination in the PLC Cabinet - MD6640	DATE 8/24/2022	CHG NO 00	NUMBER 1.10-220825-1

4.0 Benefits


This best practice results in the following:

- A source of sufficient lighting in the PLC cabinet that is available with “the flip of a switch”.
- More efficient and effective maintenance/repair work and inspections as the technicians/inspectors can focus on the actual work/inspections instead of trying to provide sufficient lighting to be able to work/inspect.

Before:



After:



Lamp installation location:



THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Illumination in the PLC Cabinet - MD6640

DATE
8/24/2022

CHG
NO
00

NUMBER
1.10-220825-1

5.0 Resources Required

ITEM	DESCRIPTION	PN	QUANT.
1	Reflector de 24V	487-7586	01
2	Switch	530-6765	01
3	Cabo	486-8751	01

MANPOWER	1
REPAIR TIME	4
SUPPLY	4

6.0 Supporting Attachments / References

Electrical schematic drill MD6640.

7.0 Related Best Practices

N/A

8.0 Acknowledgements

Special thanks to the efforts of the engineering team at Sotreq Salobo, always willing to offer support in the development of solutions for partners and customers, and other participants involved in this project.

Responsible for implementation:

Josinei Valentim
Fleet Performance Engineer
Sotreq S/A

Diego Ferreira
Inspector
Sotreq S/A

Rodrigo Barros
Mechanic
Sotreq S/A

Franciné Silva
Mechanic
Sotreq S/A

Raissa Nascimento
Fleet Performance Engineer
Sotreq S/A

Isaac Pedrosa
Engineer Coordinator
Sotreq S/A

THE INFORMATION HEREIN MAY NOT BE COPIED OR TRANSMITTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF CATERPILLAR

Illumination in the PLC Cabinet - MD6640	DATE 8/24/2022	CHG NO 00	NUMBER 1.10-220825-1
--	-------------------	-----------------	-------------------------