


Less precise measurement process

Number of measurements


75
50
25
0



More precise measurement process

Number of measurements

75
50
25
0



Observed value

40

45

50

55

60