

```
G75 X0 z0
T1 D1
G96 S200 LIMS=1500 M03
M08
G00 X36 Z2
CYCLE95("AB:BC",1,0.2,0.4,0,0.15,0.1,0.05,9,,,)
G00 X36 Z2
G75 X0 Z0
M05
M09
M30
AB:
G01 X0 Z0 F0.1
G01 X4.25 Z0
G01 X4.25 Z-6
G01 X7.75 Z-6
G03 X23.75 Z-14 CR=8
G01 X23.75 Z-24.5
G01 X28.75 Z-27
G01 X30 Z-27
G01 X30 Z-30
G01 X32 Z-30
BC:
```