Revision B – 31/10/2025


# 020221 Work Procedure

## Traffic Sign Recognition (TSR) Update – NO ADR


**ENSURE BATTERY CHARGER IS CONNECTED TO VEHICLE PRIOR TO COMMENCING SOFTWARE UPDATE**

1. Turn Ignition on to permanent IGN mode - Permanent IGN is displayed on instrument cluster


2. Click on **USB Token or Certificate**




3. Click on **All ECU**





4. Click on **FRCAM_2236**




5. Click on **ECU Update**





6. Place cursor in text box




7. Type in **70JB412A412B** and click **Next**





8. Click **Next**




9. Click **Next**





10. Click **Next**




11. Click **Next**





12. Click **Next**




13. Click **Next**





14. Click **Next**




15. Click **Next**





16. Click **Next**




17. Click **Send**





18. Click **Next**




19. Click **Next**





20. Click **Next**




21. Click **Next**





22. Click **Next**




23. Click **Finish**





24. Click **FRCAM_2236**




25. Click on **ECU Update**





26. Place cursor in text box




27. Type in **70JB412B412A** and click **Next**





28. Click **Next**




29. Click **Next**




30. Click **Next**




31. Click **Next**





32. Click **Next**




33. Click **Next**





34. Click **Next**




35. Click **Next**





36. Click **Next**




37. Click **Send**





38. Click **Next**




39. Click **Next**





40. Click **Next**




41. Click **Next**





42. Click **Next**




43. Click **Finish**





44. Click on **FRCAM_2236**




45. Click here





46. Click **Yes**




47. Click on **Identification**





48. Click here




49. Click on **Print**





50. Click on **Desktop**



51. Place cursor in the **File name** text box





52. Enter last 4 digits of vehicle VIN and **Save** the ECU Identification file (or if file name already exists save a copy – do not overwrite)




53. Make the ECU Identification file available to the Warranty Administrator for attachment to the claim.


54. Click here





55. Click here




56. Click here





57. Click on **All DTC**



58. Click here




59. Click on **Yes**




60. Turn vehicle off.
61. Lock vehicle.
62. Take keys away from vehicle and leave locked for 15 minutes before attempting any other updates

B

63. **If DTCs are present following the update and will not clear, carry out a power latch (IGN OFF, lock the vehicle and remove the cards from the vehicle) for 15 minutes and recheck the vehicle for codes following this procedure.**