Revision E – 29/04/2026


020222 Work Procedure

Traffic Sign Recognition (TSR) Update –ADR00


ENSURE BATTERY CHARGER IS CONNECTED TO VEHICLE PRIOR TO COMMENCING SOFTWARE UPDATE

1. Turn Ignition on to permanent IGN mode - Permanent IGN is displayed on instrument cluster

2. Click **USB Token or Certificate**




3. Click here




E


4. Click on **FRCAM_2236**




5. Click on **ECU Update**




6. Place cursor in text box




7. Type in **70JB410B410C** and click **Next**




8. Click **Next**




9. Click **Next**



10. Click **Next**




11. Click **Next**




12. Click **Next**




13. Click **Next**




14. Click **Next**




15. Click **Next**




16. Click **Next**




17. Click **Send**




18. Click **Next**




19. Click **Next**




20. Click **Next**




21. Click **Finish**




22. Click **FRCAM_2236**




23. Click on **ECU Update**




24. Place cursor in text box




25. Type in **70JB410C410B** and click **Next**




26. Click **Next**




27. Click **Next**




28. Click **Next**




29. Click **Next**



30. Click **Next**




31. Click **Next**




32. Click **Next**




33. Click **Next**




34. Click **Next**




35. Click **Send**




36. Click **Next**




37. Click **Next**




38. Click **Next**




39. Click **Finish**




40. Click on **Identification**




41. Click here




42. Click on **Print**




43. Click on **Desktop**



44. Place cursor in the **File name** text box




45. Enter last 4 digits of vehicle VIN and **Save** the ECU Identification file (or if file name already exists save a copy – do not overwrite)




46. Make the ECU Identification file available to the Warranty Administrator for attachment to the claim.

47. Click here




48. Click here




49.


50. Click here




51. Click on **All DTC**



52. Click here



53. Click **Yes**



54. Turn vehicle off.
55. Lock vehicle.
56. Take keys away from vehicle and leave locked for 15 minutes before attempting any other updates
57. **If DTCs are present following the update and will not clear, carry out a power latch (IGN OFF, lock the vehicle and remove the cards from the vehicle) for 15 minutes and recheck the vehicle for codes following this procedure.**

A