ADVISORY HOTLINE FIX

Group: 54 – Chassis Electrical	**Original Date: 11/02/2019**	**No.** ALL54-001
Model: All	**Subject:** Condensation in tail lamps.	
Revised on ..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Gary Van Gils National Service Manager Service Operations	
MMAL Ref TSL1504036-A	Document consists of 6 pages.	

1. **Subject**: Condensation in tail lamps.

2. **Possible Cause**: The condensation is a natural phenomenon and is not indicative of a manufacturing defect. As a tail lamp assembly heats up during operation, the air inside the tail lamp becomes hot and expands. As the tail lamp cools, the air contracts and draws moisture into the tail lamp. Moisture that occurs as a result of this process should generally dissipate in approximately 1 hour, in a dry warm environment.

   Tail lamps should not be replaced for this concern, unless an occurrence of improper sealing is located.

3. **Field Fix:** Unless a clear manufacturing defect can be found and results in standing water in the tail lamp, tail lamps should not be replaced as this will not rectify the phenomenon. The presence of moisture in the tail lamps is a normal phenomenon and should be explained to the customer.

4. **Warranty Information:** Not applicable.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.*

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.