ADVISORY HOTLINE FIX

Group: 54 – Chassis Electrical	**Original Date:** 11/02/2019	**No.** ALL54-002
Model: All	**Subject:** Condensation in headlamps.	
Revised on ..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Gary Van Gils National Service Manager Service Operations	
MMAL Ref TSL1504035	Document consists of 1 page.	

1. **Subject**: Condensation in headlamps.

2. **Possible Cause**: Due to headlamp design, under normal operating conditions, condensation may occur in the headlamp assembly under some environmental conditions. This is not a product defect.

3. **Field Fix:** There is no rectification for this normal condition of condensation in headlamp, as it is due to environmental factors. As a headlamp assembly heats up during operation, the air inside the headlamp becomes hot and expands. As the headlamp cools, the air contracts and draws moisture into the headlamp.

   If a vehicle presents with condensation in headlamps, the lamps should be left on for one hour, and the level of condensation should be monitored. If moisture is still present after one hour, Dealers should investigate for possible causes of water entry. If condensation disappears after one hour of operation, this is considered to be a normal phenomenon.

   Headlamps should not be replaced unless an occurrence of improper sealing is located.

4. **Warranty Information:** Not applicable.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.*

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.